

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name <b>N.M. "W" State</b>	
2. Name of Operator <b>Sun Oil Company</b>		8. Farm or Lease Name <b>1</b>	
3. Address of Operator <b>P. O. Box 1861 Midland, Texas 79701</b>		9. Well No. <b>Wildcat</b>	
4. Location of Well UNIT LETTER <b>C</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1900</b> FEET FROM THE <b>West</b> LINE, SECTION <b>16</b> TOWNSHIP <b>20-N</b> RANGE <b>6-W</b> NMPM.		10. Field and Pool, or Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) <b>GR 6836</b>		12. County <b>McKinley</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Intent to P & A as follows:

1. Set Plug #1 w/78 sx. cmt. @ 10422' - 10200'
2. Set Plug #2 w/203 sx. cmt @ 9800' - 9400'
3. Set Plug #3 w/35 sx. cmt. @ 9000' - 8900'
4. Set Plug #4 w/50 sx. cmt. @ 5300' - 5100'
5. Cut 8-5/8" Csg. @ 1215' Puld & Rec. 1200'
6. Set Plug #5 w/91 sx. cmt. @ 1225' - 1025'
7. Set Plug #6 w/63 sx. cmt. @ 420' - 320'
8. Set Plug #7 w/17 sx. cmt. @ 30' - 0'
9. Set dry hole marker.
10. Fill pits and clear location

*E.C. Arnold*

Permission to plug given verbally by Joe Ramey.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>James L. Boren</i></u>	TITLE <u>Administrative Clerk</u>	DATE <u>2-15-73</u>
APPROVED BY <u><i>Ernest C. Clark</i></u>	TITLE <u>SUPERVISOR DIST. #3</u>	DATE <u>FEB 16 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		