

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well Oil 2. Name of Operator Northern Minerals 3. Address & Phone No. of Operator c/o NMOCD, 1000 Rio Brazos Road, Aztec, NM 87410 4. Location of Well, Footage, Sec., T, R, M Unit J, Sec. 16, T-16-N, R-6-W, NMPM, McKinley County	API # (assigned by OCD) API #30-031-20434 5. Lease Number 6. State Oil&Gas Lease # 7. Lease Name/Unit Name Santa Fe Pacific Railroa 8. Well No. #16 9. Pool Name or Wildcat Gallup 10. Elevation:
---	--

Type of Submission	Type of Action
☐ Notice of Intent	☒ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☐ Other -
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut off
	☐ Conversion to Injection

13. Describe Proposed or Completed Operations

Plugging Summary:

8-18-99 MO, RU. ND wellhead and NU BOP, test. Found packer stuck. Work tubing. Pump ¼ bbl water down casing and pressured up to 500# for 5 min, held OK. Pressure up to 750# and then blew hole in tubing.

8-19-99 RIH with wireline sinker bars, stacked out at 771'. TIH with 1-13/16" jet cutter and cut tubing at 750'. PU on tubing pulling 40,000#, could not pull tubing free. Determined there was approximately 15' of tubing to packer. Work tubing and free packer. Pull packer. PU and TIH with 1-1/4" tubing workstring. Tag bottom at 790'. Establish circulation out casing. Plug #1 with 25 sxs Class B cement with 2% CaCl₂ from 790' to 466'. TOH with tubing and WOC for 3 hours. TIH with tubing and tag cement at 558'; LD tubing. Load casing with 1 bbl water and pressure test to 500# for 5 min, held OK. Perforate 2 bi-wire squeeze holes at 130'. Load hole with 1/8 bbl water and pressure up to 500#. TIH with tubing to 260'. Plug #2 with 28 sxs Class B cement inside casing from 260' to surface, circulate cement out 4-3/4" casing. LD tubing. WOC.

8-20-99 Safety Meeting. PU 1 joint and tag cement 12' from surface, LD. RD tubing equipment and ND BOP. Dig out and cut off 4-3/4" casing. Mix 8 sxs Class B cement, top off 4-3/4" casing and install P&A marker. RD rig and equipment; move off location.

H. Villanueva, NMOCD was on location and approved all procedures.

SIGNATURE William F. Clark Contractor

September 22, 1999

(This space for State Use)

Approved by H. Villanueva

DEPUTY OIL & GAS INSPECTOR, DIST. 4

Title

Date

SEP 29 2000

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

15691

Rig No 74

Date Wed 8-15-99

Well No SFPRR #16 Location N-E Sec. 29 T-16-N R-6-W Company AMOCO / NORTHERN MINERALS

FROM	TO	DESCRIPTION OF OPERATION
12:30	1:00	Road Rig + Equip To Loc.
1:00	1:30	R-U Rig + Equip,
1:30	2:30	N-D Well Head N-D Flange & BOP Test BOP, R-u TBG equip.
2:30		Pump TBG Packer Stock, Work TBG Pump 3 BBLS Water Down The TBG @ 1/4 BPM @ 600#, no circulation at Blow Out The Csg. Pump 1/4 BBL water down the csg & Pressure up to 500# Held 5 min ok Pressure up to 750# & Blow Hole in the TBG. circulating out the TBG. Work TBG. Could not work Packer Free SHUT well in SOFW.
		(11 Hrs)
		HENRY VILLANUEVA W/ NMCO WAS IN LOC.

Fuel & Motor Oil _____ Water Hauled 1-LOHD (A-PLUS)

Rental Equipment _____ Cement Retainers _____

Cementing

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Robert Whiteley	25		
Operator	Humberto Fierro	16		4
Helper	Vincent Bizzell			4
Helper	Alfred Fierro			4
Helper	Mr. Fournier			4

COST 1,828.07

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

15692

Rig No # 11

Date THU 8-19-79

Well No SFRR # 16 Location Company WMACO / Western Minerals

FROM	TO	DESCRIPTION OF OPERATION
11:30	12:00	TRAVEL TO LOC.
12:00	12:30	START R.O. & EQUIP. H-10 SAFETY OIL (TOPIC) RESPIRATORS
12:30		R-O WIRELINE T.H. WITH SINKER BARS & STACK OUT @ 771' POOH
	1:00	T.H. WITH 1 13/16" JET CUTTER & CUT TBG @ 750' POOH
1:00	1:30	PULL TO TBG PULLING 40,000# COULD NOT PULL TBG FREE
1:30		PUMP DOWN THE TBG WITH 3 BBLs WATER @ 1/2 BPM @ 750# NO
		CIRCULATION OUT THE CSG, PUMP DOWN THE CSG WITH 1/2 BBL WATER
		+ BREAK CIRCULATION OUT THE TBG, MIX & PUMP 4 SKS CEMENT &
		PUMP DOWN THE CSG & RETURN OUT THE TBG. SHOWS TO BE
	1:30	APPROX 15' OF TBG TO PACKED
1:30	12:00	RUN WIRELINE & CHECK COLLARS DOWN TO 266' POOH
12:00		WORK TBG & WORK PACKER FREE. PULL 6' SUB & PACKER. PACKER ABOUT
	12:45	LET PULL THROUGH WITH HEAD
12:45		R-O BOP & WELL HEAD, GRIP PACKER OUT THE BOTTOM OF WELL HEAD.
	12:00	R-O WELL HEAD, & BOP. TEST BOP. R-O TBG EQUIP FOR 1 1/4" TBG.
12:00	12:50	TRAILY & P-O 1 1/4" (A-PLUS WORKSTRING) & TBG BOTTOM @ 770'
12:50		BREAK CIRCULATION OUT THE CSG WITH 1 BBL WATER, PLUG #1 MIX &
	12:45	PUMP 25 SKS CEMENT WITH 2% CASH FROM 770' TO TOC @ 146'
12:45	1:00	L-O TBG TO 455' POOH. SHUT WELL IN.
1:00	4:00	LOC.
4:00	4:15	T.H. WITH 1 1/4" TBG & TBG TOC @ 538'
4:15	4:30	L-O ALL THE TBG.
4:30	4:40	LOAD THE HOLE WITH 1 BBL WATER. TEST CSG TO 500# HOLD 5 MIN OK.
4:40	5:00	R-O WIRELINE T.H. & PERFORATE 2-1 1/16" HOLES @ 130' POOH. R-O WIRELINE.
5:00	5:05	LOAD THE HOLE WITH 1/8 BBL WATER, & PRESSURE UP TO 500#.
5:05	5:15	P-O 1 1/4" TBG TO 260'
5:15		PLUG #2 MIX & PUMP 28 SKS CEMENT FROM 260' WITH 900 CEMENT. RETURNS
	5:30	LET 1 1/2" CSG
5:30	5:40	L-O 1 1/4" TBG. SHUT WELL IN SOFA

13 1/2 HRS

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing P-#1-25 SKS P-#2-28 SKS

Wireline 1-1 1/16" JET CUTTER 2-1 1/16" HOLES @ 130'

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	ROBERT WHITELEY	25		
Operator	HILBERTO FLEDO	16		13 1/2
Helper	VINCENT BIZZELL			13 1/2
Helper	CLARK FLEDO			13 1/2
Helper	ANTONIO SOTO			13 1/2

POST 5,315.52

Date 8-19-79

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499

505-325-2627 • FAX (505) 325-1211

10693

Rig No 71

Date Fri 8-20-99

Well No SEPRR #16 Location _____ Company Amoco / Southern Natural

FROM	TO	DESCRIPTION OF OPERATION
4:50	6:00	TRAVEL TO LOC.
6:00	6:30	START R.O + EQUIP. H.L.D SAFETY MEY (TAPIC) N-D.
6:30	7:35	R-O LOT + TAD TAC 12' FROM SURFACE. L-O ONE IT,
7:35		R-O FOR EQUIP. N-D REP. BIG OUT + CUT OFF 4 $\frac{3}{4}$ " CSG,
		EASTAN MARKED WITH 8 SRS CORRECT 1 SK TO TOP OFF 4 $\frac{3}{4}$ " CSG
	8:00	+ 7 SRS FOR THE MARKER
8:00	10:00	R-O R.O + EQUIP. MOL
		(5½ Hrs)
		HENRY KULIAVSKAYA G1 / SUMMER GLASS ON LOC

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing 1042167 8 565

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	ROBERT Whiteley	25		
Operator	Humberto Fierro #113 to #111 3HRS	16		8 1/2
Helper	VINCENT Bizzell			5 1/2
Helper	MARK Fierro			5 1/2
Helper	ANTHONY SUTA #104 to 100 3HRS			8 1/2

COST 1,719,37

Date 8-20-99

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

10694

Rig No 44

Date mon 8-23-79

Well No SEPRR 76 Location _____ Company UNICED / Southern oil fields

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	ROBERT HINLEY	25		
Operator	ALBERTO FIERO	16		12
Helper	VINCENT BIZZELL			12
Helper	CHUCK FIERO			1 1/2
Helper	ANTONIO SOTO			12

Date 8-23-99