Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED			
Budget Bureau No. 1004-0135			
Expires: March 31, 1993			

Expires: March 31, 1993

5. Lease Designation and Serial No.

		NOO-C-14-20-4402	
SUNDRY NOTICES A	6. If Indian, Allottee or Tribe Name		
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		NAVAJO	
SUBMIT I	7. If Unit or CA, Agreement Designation		
1. Type of Well			
Other	8. Well Name and No.		
2. Name of Operator BASIN FUELS, LTD.	NOO NAVAJO #3		
3. Address and Telephone No.	-30-031-20529		
P.O. BOX 50 FARMINGTON, NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Desc	10. Field and Pool, or Exploratory Area FRANCISCAN LAKE M		
•	11. County or Parish, State		
1650' FNL x 1650' FEL SEC. 13 T20N R6W		MCKINLEY NM	
	TO INDICATE NATURE OF NOTICE REPO		
TYPE OF SUBMISSION	ECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA E OF SUBMISSION TYPE OF ACTION		
	<u> </u>		
☐ Notice of Intent	Abandonment Recompletion	Change of Plans New Construction	
Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing	Conversion to Injection	
	Other	Dispose Water	
į		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
	ertinent details, and give pertinent dates, including estimated date of startir depths for all markers and zones pertinent to this work.)*	ng any proposed work. If well is directionally drilled,	
	DING TO THE ATTACHED REPORT ON 9-16	-96	
2) DESTODATION AND DESERVING	OF LOCATION WAS COMPLETED ON /△-30	3-96	
2.) RESTORATION AND RESEEDING (of Location was completed on 70 30		
	والمساوية والموارد والمراجع والمواجع والمراجع وا	e e e e e	
	DEGERME		
	DEGEINE	The state of the s	
	No. 1 0 1898	y Samuel	
	בייי אורף וייי אוריי		
	OM CON. DI	W.	
	6/21. 2		
4. I hereby certify that the foregoing is true and correct			
Signed Bradly It Falzman	Agent Title	Date 12-5-96	
(This space for Federal or State office use)	A	PPROVED	
Approved by	Title	Date	

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

Basin Fuels, Ltd.

September 17,1996

NOO Navajo #3 (Mesaverde) 1650' FNL, 1650' FEL, Sec. 13, T-20-N, R-6-W McKinley County, NM., NOO-C-14-20-4402

Plug & Abandonment Report

Cementing Summary:

Plug #1 with 46 sxs Class B cement inside casing from 2709' to 2103' to cover Mesaverde perforations.

Plug #1b spot 37 sxs Class B cement inside casing from 2176' to 1688' to cover Mesaverde top.

Plug #2&3 with 66 sxs Class B cement inside casing from 1267' to 397' to cover Chacra and Pictured Cliffs tops.

Plug #4 with 44 sxs Class B cement pumped down 4-1/2" casing from 150' to surface, circulate good cement out bradenhead.

Plugging Summary:

Notified BLM 6:00 am, 9/12/96

- 9-12-96 Road rig and equipment to location. RU rig. Layout relief line to pit. Check well pressures: casing 50#, tubing and bradenhead 0#. Bleed well down. Load tubing with 8 bbls water. Attempt to pressure test tubing; leak 1/8 bpm at 600#. Work rods and unseat pump. POH and LD 105 ¾" rods and pump and 14' of pony rods. Total rod length in well, 2665' with polish rod. ND wellhead. NU BOP and 7-5/8" flange. Test BOP; OK. Change over for tubing and RU tubing equipment. Shut in well. SDFD.
- 9-13-96 Safety Meeting. PU tubing and RIH; tag bottom at 2709'. Pump 20 bbls water down tubing. Plug #1 with 46 sxs Class B cement inside casing from 2709' to 2103' to cover Mesaverde perforations. POH and tally 83 joints 2-3/8" tubing. Shut in well and WOC. RIH with tubing and tag cement at 2176'. Load casing with 21 bbls water and circulate clean. Pressure test casing to 500# for 5 min, held OK. Plug #1b spot 37 sxs Class B cement inside casing from 2176' to 1688' to cover Mesaverde top. POH to 1267'. Combine Plug #2 and #3 with 66 sxs Class B cement inside casing from 1267' to 397' to cover Chacra and Pictured Cliffs tops. POH and LD tubing. Shut in well and SDFD.
- 9-16-96 Safety Meeting. Open up well. Dig out wellhead. RU A-Plus wireline truck. Perforate 3 HSC squeeze holes at 150'. Establish circulation out bradenhead with 5 bbls water. Plug #4 with 44 sxs Class B cement pumped down 4-1/2" casing from 150' to surface, circulate good cement out bradenhead. Cement tried to flow back. Shut in well and WOC. ND BOP. Cut wellhead off, cement at surface. Mix 10 sxs Class B cement and install P&A marker. RD rig and equipment. Move off location. Attempt to move to Easter Flats #1; rig stuck in mud.

Ronnie Snow with BLM on location.