UNITED STATES DEPARTMENT OF THE INTERIOR

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	5. LEASE ជាគីប្រងឺ ១ ខ្លួនថា N.M. 8896 មិត្តិគីថា ៤ ប៉ុន្តិទី
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
1 all goa	8. FARM OR LEASE NAME STEPPIN OUT STEPPIN
well XX well other	9. WELL NO. 9 5 4 5 5
2. NAME OF OPERATOR BASIN FUELS, LTD.	No. 1 STATE TO SELECT NAME TO SELECT
3. ADDRESS OF OPERATOR 87401	FRANCISCAN LAKÉ- MESA VERDE
Suite 300, 300 W. Arrington, Farmington, N.M.	11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	Sec.18, T20N, R5W 🚆 💆 🚆
AT SURFACE: 1980' FSL and 2310' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE 5
AT TOTAL DEPTH:	McKINLEY SAFA NEW MEXICO
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. Proposition of the control of the contr
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6746 Ground 휴전도 및 물론으로
TEST WATER SHUT-OFF [] []	
FRACTURE TREAT	9.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [change on Form 9–330.) = 🚊 🖔 😑
MULTIPLE COMPLETE	distribution of the control of the c
ABANDON*	idealy in idealy in idealy in a second control of the control of t
(other)	ensithibitize to har a common of the common
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
02/27/79 Move in rotary tools- L & B speed drill	
02/28/79 Rig up. Spud 12¼" hole at 11:00 AM, drill to 45% and	
shut down for night.	
03/01/79 Drilling at 65'. Down for rig repairs.	
04/06/79 Drill 12½" hole to TTD of 95'. Run 2 jts. 8 5/8" 24.0# = 55.52	
K-55 casing and set at 87'. Cement with 60 sacks class "B"	
and 2% CaCl2. Circulated estimated 10 sacks cement? Plus ?	
down. 8:00 PM 04/06/79. Install BOP and test same. ਪ੍ਰੈਨਿੰਡ ਸਿੰਘ ਸਿੰਘ ਸਿੰਘ ਸਿੰਘ ਸਿੰਘ ਸਿੰਘ ਸਿੰਘ ਸਿੰਘ	
rreparing to drill out.	ad inclement weather. 2 jts. 8 578" 24.0# " " " " " " " " " " " " " " " " " " "
Subsurface Safety Valve: Manu. and Type	Ft.
18. I hereby certify that the foregoing is true and correct	1.00 mg/s/ 1.00 m
SIGNED JACK D. COOK TITLE AGENT	DATE April 18, -1979
(This space for Federal or State office use)	
APPROVED BY TITLE	DATE TO STATE TO STAT
CONDITIONS OF APPROVAL, IF ANY:	
	water of the control
	And Complete the control of the cont
*See Instructions on Reverse Side	
COST COST	