

opies  
ale  
rice

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

II  
1980, Hobbs, NM 88240  
II  
Drawer DD, Artesia, NM 88210  
III  
0 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30031-20718
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <del>Capital</del> Lisa Lynn
2. Name of Operator Baca Petroleum Corp.	8. Well No. 1
3. Address of Operator 165 South Union Blvd. #460, Lakewood, Co. 80228	9. Pool name or Wildcat Entrada
4. Well Location Unit Letter <u>M</u> : 1036 Feet From The South Line and 330 Feet From The West Line Section 28 Township 16 Range 6W NMPM McKinely County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER: <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 25 sx cmt (183 foot plug) from 3012' to 2829'.
2. Set 10 sx cmt (73 foot plug) at 5' to 78'.
3. Cut off well head and set dry hole marker.
4. Level out location.

**RECEIVED**  
FEB 26 1990  
OIL CON. DIV  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ralph R. Wilkerson TITLE Vice President Production DATE 2/23/90  
TYPE OR PRINT NAME Ralph R. Wilkerson (303) 969-8146 TELEPHONE NO.

(This space for State Use)

APPROVED BY Denny J. Foust TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAY 29 1991  
CONDITIONS OF APPROVAL, IF ANY: