## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

**DISTRICT 1** 

CONDITIONS OF APPROVAL, # ANY:

## OIL CONSERVATION DIVISION

Form	C-1	103	
Revis	ed 1	-1-8	9

P.O. Box 1980, Hobbs, NM 88240  P.O. Box 2088  DISTRICT II P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410		WELL API NO. 30-031-20414			
		5. Indicate Type of Lease			
		STATE FEE X  6. State Oil & Gas Lease No.			
7777,747, 67410			C. State Off & Gar Leage No.		
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESE	RVOIR. USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name		
OIL X GAS WELL	OTHER	<i>*</i>	BULLSEYE		
2 Name of Operator Nerdlihc Company, In-	0		8. Well No.		
3. Address of Operator			9. Pool name or Wildcat		
337 E. San Antonio D: 4. Well Location	rive, Suite 101, Long E	Beach, CA 90807	Mulestin Wall		
	40 Feet From The South	Line and1560	Feet From TheWest Line		
Section 18	Township 16N R	inge 9W	NMPM McKinley County		
	10. Elevation (Show whether		NMPM FICKIFIE'S County		
11. <b>C</b> heck	Aista Pay to Indicate I	Notion of Notice D			
NOTICE OF IN	Appropriate Box to Indicate 1		- · · ·		
PERFORM REMEDIA WORK	W PLUS AND ABANDON		SEQUENT REPORT OF:		
1234	11 59	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON FEB	2 1938 HANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT X		
PULL OR ALTER CASING TEST AND CE OTHER: OTHER: OTHER:		MENT JOB			
OTHER: DIGGE		OTHER:			
12. Describe Proposed or Completed Oper	ations (Clearly state all pertinent details, as	d give pertinent dates, includ	ing estimated date of starting any proposed		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  9/28/97 MIRU P&A equipment					
		of fish @ 578'. 1	POH, TIH w/ overshot and 2 3/8"		
tbg., get on 2 3/8"	collar, jar fish free,	POH, lay dn fish	hing tool and junk tbg., TIH		
w/ 3 3/4" bit and tbg., break circulation with H <sub>0</sub> O, drill out CIBP @ 931'.					
9/30/97 Finish dril	ling out CIBP and push	to 1942', mix an	nd pump 15 sx class H cmt.,		
(well would not circulate) sd 2 hours WOC, break circulation with full returns, pump					
35 sx class H cmt., POH with tbg. to 1500', circulate tbg., clean, POH to 1000',sdfn. 10/1/97 TIH w/ tbg., tag TOC @ 1500', POH w/ tbg. to 1200', break circulation, pump					
40 sx class H cmt. POH w/ tbg., TIH w/ csg. cutter and tbg., cut csg @ 154', POH w/ csg					
cutter, POH w/ 154'	4 1/2' csg., TIH w/ tbg	to 210', break	circulation, circulate cmt		
from 210' (56' in cs	g stub) to surface, POH	w/ tbg., top su	irface csg off w/ cmt.,		
Rig down, clean loca	tion, install dry hole	marker.			
I hereby certify that the information above is to	ue and complete to the best of my knowledge and	belief.			
SIGNATURE ASSOCIATION A	## mm	LE 113.5.2-1	DATE 1/28/58		
TYPE OR PRINT NAME	E 4.16		TELEPHONE NO.		
(Thu space for State Use)					
ATROVED BY Johnny R	olivison m	DEPUTY OIL & GAS II	NSPECTOR, DIST. #3 FEB 2 1998		