ubmit 3 Copies Appropriate	State of New Mexico Energy, Minerals and Natural Resources Department					Form C-103 Revised 1-1-89				
sistrict Office	OIL CONSERVA	ATION D	IVISION							
ISTRICT I	P.O. Box 2088				WELL API NO.					
O. Box 1980, Hobbs, NM 88240	Santa Fe, New Mexico 87504-2088				30-031-20825					
DISTRICT II					5. Indicate Type of Lease					
O. Drawer DD, Artesia, NM 88210						STATE X FEE				
DISTRICT III		100	7. 10	- 1			T PEL			
100 Rio Brazos Rd., Aztec, NM 87410					6. State Oil & Gas Lease No. LH-3667					
			mnd Silve							
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					7. Lease Name or Unit Agreement Name					
			BACK TO A		7. Lease Name or Un	nt Agreement Nam	5			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					000.4700					
(FORM C-101) FOR SUCH PROPOSALS.)					STATE					
1 Top of Wall										
1. Type of Well OIL WELL X	GAS OTHER WELL	:								
2. Name of Operator					8. Well No.					
ROBERT L. BAYLESS					9. Pool name or Wildest					
3. Address of Operator	TADAMICTON AND 97400	2								
P.O. BOX 168 FARMINGTON, NM 87499					Miguel Creek Gallup					
4. Well Location	1650 7 15 4	SOUTH	Line and	990	Feet from The		WEST	Line		
Unit Letter L	: 1650 Feet from the	300111	Line and							
. 16	Township 16N	Range	6W		NMPM	McKINLEY	Coun	ity		
Section 16	10. Elevation	(Show wh	ether DF, RKB, F	T, GR,						
<u> </u>	eck Appropriate Box to In	ndicate Nat	ure of Notic	e Re	nort or Othe	r Data				
		idicale Ival	l c	U, ICC	EQUENT R	EDORT C	rE ·			
NOTICE OF	INTENTION TO:		ì							
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WOR	K	<u> </u>	ALTERING (CASING			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING	OPNS.	PLUG AND A	BANDONMENT			
TEMPORANET ABANDON			CACING TEST	ND CE	MENT IOR					
PULL OR ALTER CASING			CASING TEST	AND CE	MENT JOB					
OTHER:		_ [_]	OTHER:							
12. Describe Proposed or Compl	eted Operations (Clearly state of	ill pertinent deta	ails, and give per	inent d	ates, including esti	mated date of .	starting any pro	posed		
work) SEE RULE 1103.	eled Operations (Clearly State 2	portunosa aust	and and green part							
Robert L. Bayle	ess intends to plug and abandor	ı this well. T	The procedure i	s attac	hed.					
•										
	1									
	/_/I						 -			
I hearby certify that the information ab	ove is true and complete to the bell of my kno	wiedge and belief.						,		
			CNCINCED			TNATE		2/1	32	
SIGNATURE	e / / / //	TITLE	ENGINEER			DATE		0/6/6	,	
	, - , , , , , , , , , , , , , , , ,						(505) 227 2	, 650		
TYPE OR PRINT NAME	Tom McCarthy				TELEPHO	NE NO.	(505) 327-2			
(This space for Stat	GINED BY OHAPLE T. POTTO	H JE	PUTY WALL MA	ن الله	PROBA, bein	***	JUN	1020	12	
APPROVED BY		TITLE				DATE		# 0 LUI	<i></i>	

Robert L. Bayless Plug and Abandon Procedure

State No. 8 1650' FSL & 990' FWL, Section 16, T16N, R6W McKinley County, NM

Well data:

Surface Casing: Unknown at 100'. Assume 8 5/8" since this was used in the other wells.

Production Casing: None.

TD: 100'
PBD: 100'
Perfs: None.
Tubing: None.
Rods: None.

- 1. Move in cementers. Fill hole with cement from surface. About 36 sx will be required based on above size assumption.
- 2. Shut in and WOC.
- 3. Fill casing with cement if necessary. Install P & A marker.

Notes: All cement will be Class B Neat.

Other than the cement, the well bore fluid will be 8.3 PPG water.