

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. NOO-C-14-20-5531
2. NAME OF OPERATOR James L. Ludwick	6. IF INDIAN, ALLOTTEE OR TRIBE NAME NAVAJO ALLOTTED
3. ADDRESS OF OPERATOR P.O. Box 70, Farmington, NM 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1865' FNL, 330' FEL	8. FARM OR LEASE NAME INDIAN 18
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6640 Gr.	10. FIELD AND POOL, OR WILDCAT WILDCAT Paperwash n.v.
	11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Sec. 18, T19N, R5W
	12. COUNTY OR PARISH McKinley
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

REQUEST TO PLUG & ABANDON:

Plans for Plugging Well #1-18:

1. Pull 3/4" rods & 2 7/8 tubing.
2. Fill 4 1/2" casing with water, break down perfs, fill 4 1/2" casing with 105 sks. neat cement 6% gel yield 1.73. Squeeze 5 sks cement into perfs.
3. Perfs at 1847-48, 1862-67, 1923-24, 1934-38.
4. Install dry hole marker, back fill pits and reseed location.
5. Work to be completed by June 31, 1993.

18. I hereby certify that the foregoing is true and correct

SIGNED James L. Ludwick

TITLE Operator

DATE 1/19/93

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JAN 26 1993

AREA MANAGER

\*See Instructions on Reverse Side

NMOC