

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Santa Fe Pacific 29

8. Well No.

3

9. Pool name or Wildcat

Undesignated Dakota

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

OAS
WELL ☒

OTHER

2. Name of Operator American Cometra, Inc. for
Dakota Resources, Inc.

3. Address of Operator

P.O. Box 906 Sterling City, Texas 76951

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line

Section 29 Township 17N Range 9W NMPM McKinley County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

7103 Gr.

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 09/12/92 Load hole w/ H₂O, pull 74 jts. 2 3/8" EUE tubing, inspect & rerun tubing, strap in hole, tag bottom 2481', pick tubing up 2430' break circulation to surface, spot plug #1 in 4 1/2" csg. @ 2430'-2150' w/25 sacks class "B" 2% CaCl, pull 10 St's, reverse out, W.O.C. 2 Hrs., T.I.H., tag cement @ 2195', pick tubing up to 1570' & spot plug #2, 25 sacks class "B" 2% CaCl 1570'-1290', pull 10 St's, reverse out, W.O.C. 2 Hrs. T.I.H. tag cemen @ 1305', pull and lay down tubing, perf. 4 1/2" csg. 220' break cir. to surface w/ 21 BBLS. H₂O, pump plug #3 54 sacks class "B" neat cement, circ. cement to surface out B.H., dig out cellar, cut pipe off 3' below gr., install dry hole marker, rig down. Fill and level all pits, clean up and reseed location. Ready for inspection.

RECEIVED
SEP 17 1992

OIL CON. DIV.

DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D.E. Baxter TITLE Agent for American Cometra, Inc. DATE 09/16/92

TYPE OR PRINT NAME Doyle E Baxter TELEPHONE NO.

(This space for State Use)

Original Signed by CHARLES GHOLSON

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: