

Form 3160-5
(November 1984)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

6. LEASE DESIGNATION AND SERIAL NO.
Jicarilla Contract 44

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 'D'

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

So. Lindreth Gallup/Dak

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 5 T23N R4W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO INC.

(303) 565-8401

3. ADDRESS OF OPERATOR

P.O. Box EE

Cortez, Colorado 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)
At surface

990' FNL and 990' FEL Sec 5

14. PERMIT NO.

16. ELEVATIONS (Show whether OF, AT, CR, etc.)

7082' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) long term shut-in

FEEL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

As stated by your attached correspondence dated February 24, 1989, the Jicarilla D-2 has been shut in as uneconomical since April, 1987. The subject well is capable of producing 1½ BOPD, but requires servicing to return to producing status. Texaco Inc. requests a long term shut-in status be granted for the D-2. Current market conditions prohibit servicing the well and the subject well may have future workover potential which is currently being evaluated. Your assistance and consideration pertaining to this shut-in request is appreciated.

Also, all Texaco records indicate that the Jicarilla D-2 is located in the NE NE Sec 5, T23N-R4W. Our well files make no reference to Florance-Skelly.

THIS APPROVAL EXPIRES

APR 02 1990

18. I hereby certify that the foregoing is true and correct

SIGNED

Alan A. Klier

TITLE Area Manager

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE March 23, 1989

APR 02 1989

DATE APR 05 1989

FARMINGTON RESOURCE AREA

WMOCC

*See Instructions on Reverse Side