

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 42-1144
LEASE ORIGINATOR AND SERIAL NO.
Apache Tribal No. 71

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole
2. NAME OF OPERATOR
Chace Oil Company, Inc.
ADDRESS OF OPERATOR
413 Washington, S.E., Albuquerque, New Mexico 87108
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface Unit K-Sec. 9, T-23-N, R-4-W, 1850' Southline
and 2390' West Line of Section

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla Reservation
9. WELL NO.
24-4
10. FIELD AND POOL, OR WILDCAT
Ballard
11. SEC., T., R., N., OR S.E., AND
SOUTHLINE OR AREA
Sec. 9, T-23-N, R-4-W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
N.M.

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, WT, OR, etc.)
7068 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREAT	☐	FRACURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)	☐
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☒	ALTERING CASING	☒
ABANDON*	☐	ABANDONMENT*	☒
CHANGE PLANS	☐		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting or proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sources of information to this work.)

8-15-72 Set 100' 8-5/8" Surface Casing. Cemented w/100 sxs.
8-18-72 Reached T.D. 2957' (Driller)
8-19-72 Logged (Schlumberger)
Tops: Alamo 2256'
Kirtland 2402'
Pictures Cliffs 2723'

Well Plugged and Abandoned on 8/20/72
Placed 100' plug across P.C. formation from 2675-2775' (25 sxs)
Placed 250' plug across Alamo formation from 2200-2450' (65 sxs)
Placed 50' plug bottom of surface csg. from 75' to 125' (12 sxs)
Placed 10 sxs from surface down, placed marker on location showing well and location

Reason for Abandonment - No commercial zone of production was encountered.

Shut off to plug 8/20/72

18. I hereby certify that the foregoing is true and correct
SIGNED Larry M. Long TITLE President

DATE August 20, 1972

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Larry M. Long

*See Instructions on Reverse Side