

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-B1424.5. LEASE DESIGNATION AND SERIAL NO.
Apache Tribal No. 71

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME *Cont. 71*
Jicarilla Reservation

9. WELL NO.

2-0

10. FIELD AND POOL, OR WILDCAT

Ballard *PC*11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 9, T-23-N, R-4-W

12. COUNTY OR PARISH
Rio Arriba13. STATE
N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR
Chace Oil Company, Inc.

3. ADDRESS OF OPERATOR
313 Washington, S.E., Albuquerque, New Mexico 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Unit K-Sec. 9, T-23-N, R-4-W, 1850' Southline
and 2390' West Line of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
7068 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8-15-72 Set 100' 8-5/8" Surface Casing. Cemented w/100 sxs.

8-18-72 Reached T.D. 2957' (Driller)

8-19-72 Logged (Schlumberger)

Tops: Alamo 2256'

Kirtland 2402'

Pictures Cliffs 2723'

Well Plugged and Abandoned

Placed 100' plug across P.C. formation from 2675-2775' (25 sxs)

Placed 250' plug across Alamo formation from 2200-2450' (65 sxs)

Placed 50' plug bottom of surface csg. from 75' to 125' (12 sxs)

Placed 10 sxs from surface down, placed marker on location showing
well and location

Reason for Abandonment - No commercial zone of production was encountered.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

August 20, 1972

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

