UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices	and Reports on Well	s /	
		5.	Lease Number
		· ·	Jic Contract 412
		6.	If Indian, All. or
. Type of Well			Tribe Name
GAS			Jicarilla Apache
		7.	Unit Agreement Name
. Name of Operator			
MERIDIAN OIL			
	8.		
. Address & Phone No. of Operator			Chacon Jicarilla D
PO Box 4289, Farmington, NM 874	9.	API Well No.	
10 2011 1000, 0 11 11 11 11 11 11 11 11 11 11 11 11 1			30-039-22195
. Location of Well, Footage, Sec.,	T, R, M	10.	Field and Pool
1850'FSL, 1850'FWL, Sec.9, T-23-N, R-3-W, NMPM		1.1	West Lindrith Gal/Dh
		11.	County and State Rio Arriba Co, NM
			RIO AFFIDA CO, MA
	T NAMEDE OF NOTICE	PEDORT OTHER	DATA
2. CHECK APPROPRIATE BOX TO INDICAT	E NATURE OF NOTICE	, REPORT, OTHER	
Type of Submission	Type of Ac	Change of Pl	ans
X Notice of Intent	Abandonment	New Construc	
Gul week Depart	Plugging Back	Non-Routine	Fracturing
Subsequent Report	Casing Repair _	Water Shut o	ff
Final Abandonment	Altering Casing _	Conversion t	o Injection
X	Other - Tubing re		
- -	_		
3. Describe Proposed or Completed	l Operations		
		1 1:64	and the
It is intended to repair the t	cubing and install	a plunger lift	llbore diagram
subject well according	to the attached pr	cocedure and we.	Libore dragram:
		•	the state of the s
		ſi	JEG ST.
		Į <u>l</u>	
			² JUN 2 8 1883 📝 -
			Language Company
		(0)	IL GOM. DIV.
		•••	12 12 15 12 11 1/4 12 12 14 15 15 15 15 15 15 15 15 15 15 15 15 15
			CORPUS ED TO TO
- 1			
134 /46			
14. I hereby certify that the for	egoing is true and	correct.	
Signed Wary (Machueld)	ROS9) Title Regulate	ory Administrate	or_Date 6/18/96
- Francisco	M Chief Lands and Mi	ineral Perources	
Signed Hay Machueld (This space for Federal or State Of	fige use) canos and M	merser researched	JUN 2 4 1996
APPROVED BY RIVERT KILLING	Title	Date	1330
CONDITION OF APPROVAL, if any:			

Chacon Jicarilla D #15 W. Lindrith Gallup - Dakota SW Section 9, T-23-N, R-3-W Recommended Tubing Repair Procedure

- 1. Comply with all NMOCD, BLM and Meridian safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify MOI Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. As much time as possible to the pump time is needed for the Agency to be able to show up for the cement job.
- MOL and RU workover rig. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) BOP with stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary. Have wellhead / valves serviced at A-1 Machine as needed.
- Release donut, pick up additional joints of tubing and tag bottom (record depth). TOOH with 242 jts (plus additional jts) of 2-3/8", 4.7#, J-55 EUE tubing set at 7476' (SN @ 7404'). Visually inspect tbg for corrosion, and replace any bad joints.
- 4. TIH with 4-1/2" casing scraper, 3-7/8" bit and bit sub, and clean out to PBTD at 7667. TOOH.
- TIH with tubing and land tubing near bottom perforation at 7478'. Rabbit all tubing. ND BOP and NU wellhead. Install plunger and return well to production.

Recommended: X Janful
Operations Engineer

Approved:


Drilling Superintendent

Chacon Jicarilla D #15

CURRENT

Lindrith Gallup Dakota

1850' FSL, 1850' FWL, SW Section 9, T-23-N, R-03-W, Rio Arriba County, NM Latitude/Longtitude: 36.236359 / 107.164215



Initial Potential		Production History	<u>Gas</u>	QII	Owne	ership	<u>Pipeline</u>
Initial AOF: 540 Mcfd Current SICP: 1500 psig	`	Cumulative: Current:	598.1 MMcf 50.8 Mcfd	9.6 Mbo 8.2 bbls/d	GWI: NRI: TRUST:	100.00% 81.25% 0.00%	EPNG