	The state of the s		
17 1042) (17 1042)	UNITED STATES EPARTMENT OF THE IN	SUBMIT IN TRIPLICATE (Other Institutions on the	Form approved Sudjet Butter No. 40-R1 Little Definition and settle 1
!	GEOLOGICAL SURV	EY	SF-078272
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this size for proposals to drill or to deepen or plus back to a different reservation. (Do not use this size for proposals to drill or to deepen or plus back to a different reservation.			6. IF INDIAN, ALIDETTE OF TELLOWN
1.	APPLICATION TOR PERMIT.	: such proposite)	7 000
OIL X WELL	отлія		7. UNIT ACRES MANGE
2. NAME OF OPERATOR			S. FARN OR LITTE NAME.
BCO, Inc.	/		Dunn
3. ADDRESS OF OPERATOR			9. WELL NO.
135 Grant Ave. Santa Fe, New Mexico 87501			7
4. LOCATION OF WILL (Report location clearly and in accordance with any State regulrements.* See also space 17 below.)			10. FIELD AND TOIL, OF WILDCAT .
At surface			Lybrook Gallup
1740' FSL 2160' FWL Sec. 9 T23N R7W			11. SEC., T., E. M. OR BLE AVE. BURYEY ON ARRA
			Sec. 9 T23N R7W
14. PERMIT NO.	15. ELEVATIONS (Show whe	ther pr, at, ca, etc.)	12. COUNTY ON PARISH 13. STATE
	GR 7196		Rio Arriba N. M.
	heck Appropriate Box To Indic or intention to: PELL OR ALTER CASINO	ole Nature of Notice, Report, or C	Other Data DENT REPORT OF: 4 SETTIRENO WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CARNO
SHOOT OR ACIDIZE	ABANDON*	SHOOTING ON ACIDIZING	* REANGONMENT
ELPAIR WELL	CHANGE PLANS	(Other) Rig Acciden	
(Other)		Completion or Recomple	of multiple completion on Well- etion Report and Log form.)
Pursuant to Mr. Bi	ll Bingham's request Augu	ertinent details, and give pertinent dates, constitutions and measured and true verticulars to 10, 1981, we are attached in location and subsequent of	ing Y W Drilling
Rich.	ton of the accident on ou	Trocacton and subsequent of	· Larry
•	•		
			" - " · · · · · · · · · · · · · · · · ·
·	-		RECEIVED AUG 1 3 1981
			OIL CON. COM. DIST. 3

DATE August 12, 1981

(This space for Federal or State office use)

15. I hereby certify that the foregoing is true and correct

TITLE _


President

DATE

4 W Drilling Co.

FARMINGTON, NEW MEXICO 87401

(505) 327-5218



August 11, 1981

LETTER OF ACCIDENT REPORT ON LARRY RICH

To Whom It May Concern:

Y W Drilling Company's Rig #4 had finished drilling and running casing on BCO, INC.'s Well #7, Dunn; the rig having been released at 1:00 AM, August 3, 1981, the derrick was being lowered preparing to move the rig.

The rig was being scoped down, when for some unexplained reason, Larry Rich climbed up the back side of the drawworks, stood up and evidently grabbed the drilling line and was wound up on the drum.

The drilling line was tied off and the line cut with a torch to untangle Larry Rich.

An ambulance and helicopter were dispatched to the location. Larry Rich was taken to the San Juan Regional Medical Center emergency room by ambulance.

Y W DRILLING COMPANY

Vice President of Operations

MHW/tw

copies:

BCO, INC.

USF & G USGS

BUREAU OF LAND MANAGEMENT

OSHA

OIL CON. COM. DIST. 3