
JACK A. COLE



Escrito Galco. RA \$ 05 | 7 23N R 06W U C Oper. Jack A. Cole

₩. Rincon

₹



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



IN REPLY REFER TO:

SF-078362 et al. (WC) 3162.3-1.0 (019)

NU. 1 4 1891

NOVI 5 1991
OIL CON. DIV.

Jack A. Cole PO Box 191 Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. No. 34 Rincon, Sec. 17, T. 23 N., R. 6 W., Rio Arriba County, New Mexico, lease SF-078359.
- 2. No. 6 Rincon, Sec. 5, T. 23 N., R. 6 W., Rio Arriba County, New Mexico, lease SF-078362.

The subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller Chief, Branch of Mineral Resources

2 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONE LC. TION