

II-28-1962

Stright hole test on Me dio # 2 Harry L Bagbee -0-14-1-1-3

At 500 Feet 7/8 degrees
At 1000 Feet 0 Degrees
At 1500 Feet 0 Degrees
At 2000 Feet 0 Degrees
At 2500 Feet 1/2 Degrees
At 2610 Feet 0 Degrees
At 3000 Feet 0 Degrees
At 3131 Feet 0 Degrees

These Test were ran by Lohmann Oil well servic and witness by J A Flint Jr And are correct to the best of my ~~KNOWLEDGE~~ Knowledge.

J A Flint Jr
J. A. Flint Jr

*Subscribed & sworn to before me this 28th day
of Nov. 1962*

Sophia B Ball
10-7-62



enough to get a lot of work done

enough to get a lot of work done
enough to get a lot of work done
enough to get a lot of work done
enough to get a lot of work done
enough to get a lot of work done
enough to get a lot of work done
enough to get a lot of work done
enough to get a lot of work done

and that is the only way to get a lot of work done
enough to get a lot of work done

11-88-11

11-88-11

