

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 5975

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Guadalupe Exploration Corporation		8. FARM OR LEASE NAME Taylor Ranch
3. ADDRESS OF OPERATOR P.O. Box 2087, Scottsdale, Az 85252		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' from N & E line, NE4, NE4, Sec. 26, T21N, R3W Sandoval County, New Mexico		10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T21N, R3W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) Gr. + 7086'		12. COUNTY OR PARISH Sandoval Co.
		13. STATE New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Waiting on weather

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We have set cement plug, 65 sacks, 6150' - 5950'. Ran 4 1/2 in. K-55, 9.5 lb. casing to 5845' and set with 285 sacks cement with 25% Gilsomite. We have perforated with 36 holes from 5782 to 5804 and treated with 1,000 gal. 15% acid. Well was swabbed for 4 days. Recovery was approximately 5 - 10 bbls. oil on each swab. Tubing, rods, bottom hole equipment run. Test tank is on location. Now waiting on weather to bring in pumping unit to place well on pump.

(Enclosed 4 copies of logs)

RECEIVED
MAR 13 1973
U. S. GEOLOGICAL SURVEY
FEDERAL OFFICE



18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

President

DATE

March 6, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. All necessary Federal instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional offices, are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are ~~in applicable~~ State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon wells and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed by cement plugs; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting, any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection, looking to approval of the abandonment.