

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-11424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0510073-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.	OIL WELL ☐ GAS WELL ☒ OTHER ☐
2.	NAME OF OPERATOR Grace Oil Company
3.	ADDRESS OF OPERATOR Box 1418 Christad, New Mexico 88220
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface C-NE1
14.	PERMIT NO.
15.	ELEVATIONS (Show whether DF, RT, GR, etc.) 7245 C.R.

7.	UNIT AGREEMENT NAME San Ysidro wash Unit
8.	FARM OR LEASE NAME Union Maid
9.	WELL NO. 1
10.	FIELD AND POOL, OR WILDCAT wildcat
11.	SEC., T., R., M., OR BLK. AND SURVEY OR AREA 11, 12N, R3W
12.	COUNTY OR PARISH Sandoval
13.	STATE N.Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 11-24-75 Move in. Rig up, pulling unit. Swab test Dakota perforations - swab 10 barrels watered per hour - found water to be entering bottom of shoe joint. Set CIBP at 6840 feet. Swab test Dakota perforations - swab dry with slight show of gas.
- 12-4-75 Acidize Dakota perforations 6722-64 with 1,000 gallons 15% mud acid. Swab test.
- 12-29-75 Frac. Dakota perforations with 110,000 gallons 2% KCl H₂O, 36,000 #100 mesh sand, 12,000 #20-40 sand and 25 tons CO₂. Averaging rate 37 barrels per minute. Maximum and minimum T. P. 3000 and 2700 pounds per square inch. Immediate shut in pressure - 1800 pounds per square inch - swabbed Dakota perforations at final rate of 11 barrels watered per hour with slight show of gas.
- 1-15-76 Set CIBP at 5019 feet. Swab hole dry.
- 1-16-76 Perforation Menefee 4465-4475 feet with 1 shot/ft. Attempt to swab test - no success.
- 1-17 &
1-18-76 waiting on orders

FEB 9 1976

18. I hereby certify that the foregoing is true and correct.

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well and late well site conditioned for final inspection looking to approval of the abandonment.