Form	9-331
(May	1963)

16,

## $\begin{array}{ccc} & \text{UNITED STATES} & \text{SUBMIT IN TRIPLICATE•} \\ \text{DEPARTMENT OF THE INTERIOR} & \text{(Other instructions on reverse side)} \end{array}$

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

		_
MM	701	LO
1711	1111	

	_ ! -								
	- L	c	4 T			ALLOTTER	On man	***	
	i	1).	ar 1.	אועה	. N.	VITTOTIES	OK III	BE NAV	12
SUNDRY NOTICES AND REPORTS ON WELLS	- 1								
CHRISTO RESTREE ARIES DEDICADES CARLANGELIS	1								
ALIMITA TALIBLES ATALI REFLACIS CAN MELLS									

	(Do not use this form for propos	ICES AND REPORTS ON WELLS  late to drill or to deepen or plug back to a different reservoir  TION FOR PERMIT—" for such proposals.)	
1.			7. UNIT AGREEMENT NAME
	WELL GAS WELL XX OTHER		
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Benson Mineral Group, Inc.			Federal 33-22-7
ა.	ADDRESS OF OPERATOR		
4.	3200 Anaconda Tower, 5 LOCATION OF WELL (Report location of See also space 17 below.) At surface	10. FIELD AND FOOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
	790' FSL & 1020' FEL	P	
	Section 33-T22N-R7W		Section 33-T22N-R7W
1.4	, PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
		6764 GR	Sandoval NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF I	TENTION TO:	SUBSEQUENT REPORT OF:	SUBSEQUENT REPORT OF:			
	Γ					
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF REPAIRING WELL				
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT ALTERING CASING				
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING ABANDONMENT*	<u>X</u>			
RLPAIR WELL	CHANGE PLANS	(Other)				
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)				

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

9-15-79: Spot 30 sx cmt plug at surface. Erect P & A  $\,$  marker and clean up location.



18_1 hereby certify that the foregoing frue and cor SIGNED	TITLE Production Manager	DATE Oct. 3, 1979
. This space for Federal or State office use)		DATE
OVED BY ONS OF APPROVAL, IF ANY:	TITLE	DATE

