Form approved. Form 3160-5 (November 1983) Budget Bureau No. 1004-0135 UNITED STATES

BUBMIT IN TRIPLICATED

(Other instructions on reverse aids) Expires August 31, 1985 (Formerly 9-331) 5. LEASE DESIGNATION AND SERIAL NO. NM-36936 BUREAU OF LAND MANAGEMENT 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS FOR (Do not use this form for proposals to drill or to deepen or plus McC to Annual today (Do not use this form for proposals.) N/A 7. UNIT AGREMENT NAME JUN 03 1987 WELL XX WELL N/A 07222 2. NAME OF OPERATOR S. PARM OR LEASE NAME Gary-Williams Oil Producer, Inc. BUREAU OF LAND MANAGEMENT San Isidro 15 FARMINGTON RESOURCE AREA 3. ADDRESS OF OPERATOR 9. WELL NO. 115 Inverness Drive East, Englewood, CO 80112-5116 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface 10. FIELD AND POOL, OR WILDCAT Rio Puerco Mancos 11. ESC., T., R., M., OR BLE. AND 660' FNL & 990' FWL (NW NW) Section 15-T20N-R3W NW NW 15-T20N-R3W 15. BLEVATIONS (Show whether DF. ST. CR. etc.) 14 PERMIT NO. 12. COUPTY OR PARISE | 18. STATE 6855' GR Sandova 1 16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: TEST WATER SEUT-OFF PULL OR ALTER CASING WATER SEUT-OFF REPAIRITG WELL MULTIPLE COMPLETS PRACTURE TREAT PRACTURE TREATMENT ALTERING CARING SHOOT OR ACIDIZE ARANDON* SECOTING OR ACEDISING ABANDON MBRT* REPAIR WELL CHANGE PLANS (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)Request Long Term Shut In

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) *

Gary-Williams Oil Producer, Inc. respectfully requests permission to continue the suspension of production on the above mentioned well. Current depressed oil prices make this marginal well uneconomical to produce.

There are no known problems with the casing integrity due to the fact that the cement was circulated to surface and the casing is less than 5 years old. Because of the existing condition of the well, GWOP requests that the testing requirements be waived at this time.

In the absence of an approved suspension, there may be a premature abandonment of the well and resulting loss of recoverable reserves.

Applicated Until 5/31/88 OIL CON

		promoto to the state of the state of	
18. I bereby certify that the foregoing is true and correct BIGNED MANY MUNICIPALITY	TITLE Compliance Administrato	ARPROMED	_
(This space for Federal or State offer use)		er angel	
APPROVED BY	TITLE	90N 05 198/	
~~ ×		JUN 05 198/ Juni a - level	
~~~	e Instructions on Reverse Side	Company of the second	