

6 BLM 1 Robinson 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Dry Hole**

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

330' FSL - 500' FEL

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7125' GL; 7137' RKB

5. LEASE DESIGNATION AND SERIAL NO.

NM 14970

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

B.R.'s Stars

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Undesignated Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 17, T21N, R3W, NMPM

12. COUNTY OR PARISH 13. STATE

Sandoval

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We plan to plug and abandon this well as follows:

- (1) Spot cement plug in 5½" casing from 5012' to 5461' (59 cf).
- (2) Spot cement plug 3274-3374' (13 cf).
- (3) Add a cement plug from 2765' to 2665' (to cover the top of the Chacra).
- (4) Spot cement plug 1803' - 1903' (13 cf).
- (5) Add a cement plug from 1640' to 1380' (to cover the Ojo Alamo).
- (6) Add a cement plug from 262' to 162' (to cover the 8-5/8" casing shoe).
- (7) Spot 100' cement plug 100' - surface (13 cf).
- (8) Install "dry hole marker" and restore location.

Note: We do not plan to pull casing.

We plan to P & A this well by August 31, 1987.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan
Sherman E. Dugan

TITLE

Geologist

DATE

4-1-87

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
APR 07 1987

OIL CON. DIV.
DIST. 3

APPROVED

[Signature]
DATE