

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Shogoil Ltd.

3. Address and Telephone No.

P.O. Box 29450, Santa Fe, NM 87592-9450/505474-4734

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

965' FSL & 1980' FWL Sec. 31, T21N, R2W

5. Lease Designation and Serial No.

NM NM 62577

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Chuijuilla 3114#1

9. API Well No.

10. Field and Pool, or Exploratory Area

Rio Puerco Mancos

11. County or Parish, State

Sandoval County,
New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Operator proposes to plug and abandon the well as follows:

- (1) Set a CIPB @ 4700', 58' above the top of the pfs.;
- (2) Dump a 50' cement plug on top of the bridge plug;
- (3) Perforate @ 280', circulate and cement the annulus from 57' below the base of the surface casing to the surface (approx. 30 sx.);
- (4) Set a surface plug from 50' to the surface in the 7" intermediate csg. (approx. 8 sx.);
- (5) Install a marker; and
- (6) Remove production equipment, restore the well and tank battery sites and reseed, closing and abandoning the access rd., as specified in the APD and ROW Agreement.

RECEIVED
JUN 26 1997

OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed

John B. Jones, II

Title Consulting Pet. Engineer

Date June 12, 1997

(This space for Federal or State office use)

Approved by

[Signature]

Title

Chief, Lands and Mineral Resources

Date

JUN 23 1997

Conditions of approval, if any:

CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator High Plains Pet Corp Well Name Chuijuilla 3114 #1

1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. For wells on Federal leases, Al Yepa with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Erwin Elote with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-3242.

3. Blowout prevention equipment is required.
4. The following modifications to your plugging program are to be made :

A cement plug will be placed from 273' to 173', inside the 7 inch casing, to cover the surface casing shoe.

In addition plugs will be placed inside the casing from:

** 2416' - 2516' - 50' below & above Cliffhouse*

** 1432' - 1582' - 50' below the PC & above the Fruitland*

** 1157' - 1257' - 50' below & above the Ojo Alamo*

(a)