(Formerly 9-331)	DEPARTMENT	OF THE INTE	RIOR (Other Instructions verse side)		reau No. 1004-0135 igust 31, 1985	
	BUREAU OF L	AND MANAGEME	NT	O. DESIGN	ATION AND SERIAL NO.	
SUNDRY NOTICES AND REPORTS ON WELLS					NM-6682 ·	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. 1.				The state of the s	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
ī.	APPLICATION FO	R PERMIT—" for such	Proposais.)	. /		
OIL X GAS				7 595		
2. NAME OF OPERATOR	OTHER			7. UNIT AGREEMEN	T NAME	
BCO, Inc.				8 FARM OR IT		
3. ADDRESS OF OPERATOR				i	8. FARM OR LEASE NAME Federal "B"	
135 Grant Avenue, Santa Fe, New Mexico 87501				9. WELL NO.	B	
4. LOCATION OF WELL (4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface					
At surface	low.)	an accordance with an	y State requirements.*	15 10. PIELD AND POO	L. OR WIYDOW	
1708' FSL $_{ m X}$	i ili. Euc., T b as	Gallup				
1708 FSL X 9/6' FEL Sec 27 T23N R7W				AUGUST OF 1	NE/4 SE/4	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)				Sec 27	Sec 27 T23N P711 .	
		7252' GL·	- ,, and ever)	12. COUNTY OF PAR	HEH 13. STATE	
16.	Check A			l C 1 -	New Mexico	
,	CHECK Appropriate to:	Box to Indicate 1	Nature of Notice, Report,	or Other Data		
	DESEGUENT REPORT OF:					
TEST WATER SHUT-O		II	WATER SHUT-OFF	THE PERSON AND PROPERTY OF S		
BHOOT OR ACIDIZE	MULTIPLE CO	OMPI.ETE	FRACTURE TREATMENT	- REPAIRIN	O WELL	
REPAIR WELL	ABANDON*		SHOOTING OR ACIDIZING	ALTERING	I——-1	
(Other)	CHANGE PLAN	NS	(Other)Cemer		MENT.	
17	COMPLETE		(Note: Report re Completion or Re- t details, and give pertinent d iions and measured and true v		XX .	
3/20/93	Robert Ramir Management, cement.	ez notified of intent to	Mark Kelly, Bur run long-strin	reau of Land ng casing and		
3/21/93	Robert Ramirez notified Bureau of Land Management answering machine of delay in reaching TD and new time expected to run long-string casing and cement long string casing. Reached TD of 5700' at 5:15 pm. Conditioned hole for running of casing.					
			MAR2 9 1993	23 EHH: 2	ليا	
			OIL CON. DIV	/		
I hereby certify that the	foregoing is true and corr	rect	1001. 0			
SIGNED Elizal	reth B. Keeshe	TITLEPr				
(This space for Federal	or State offer	TITLE Pr	esident	DATE 3/22	/93	
	DIRIG DECE DEC)					
APPROVED BY CONDITIONS OF APPR	OVAL IF ANY.	_ TITLE		CCEPTED FOR RE	COND	
 4 B	TAME ANI:			DATE	-	
	·			!!AR 26 1993		
	•	See Instructions of	Reverse Side	FARMINGTON DISTRICT	OFFICE	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the

SUNDRY NOTICE & REPORTS ON WELLS PAGE TWO FEDERAL B-15

Ran 123 jts of 4.5" 11.6# J-55 LT&C casing and 5 jts of 4.5" 11.6# N-80 LT&C casing. Set at 5697'. Float collar at 5654'. Marker joint at 5327' - 5334'. Used centralizers on 7 collars in Gallup and 11 other centralizers throughout string, 3 baskets and 2 turbolators. Turbolaters were used in Ojo Alamo as per NTL-FRA-90-1 with settings at 1588' and 1498'.

Cemented casing in one stage with 800 sacks 65/35 standard/poz w/ 12% bentonite, 6.25 lb/sack gilsonite, 1/4 lb/sack flocele, and 0.6% Halad-322. (Denisty = 11.3 pounds/gallon, Yield = 2.64 cubic feet/sack). Tailed in with 150 sacks Class "G" containing 8 lb/sack salt, 1/2 lb/sack flocele, 6.25 lb/sack gilsonite. (Density = 15.2 pounds/gallon, Yield = 1.38 cubic feet per sack). Displaced with 88 bbl water containing Clayfix II. Plug down at 6:25 am; bumped to 1400 psig. Float held. Circulated 41 bbl (87 sacks) slurry.

Copy of Halliburton job log is attached.

LEASE LEAVE V **JOB LOG** FORM 2013 R-2 TIME TUBING CASING 2020 Orloc with float equipment 3-21-93 0200 Safety meeting in Rig up 0210 X Rimp Tail coment @ 15.2# Drop Pling & Wash pumps & lines Pump Displacement 0625 Job Complete
Crew Riland Thanks for Calling Hall hurten Circulated 41 Bb1s coment