Distribution: O+4 (BLM); 1-Accounting; 1-Crystal; 1-File Form 3160-5 UNITED STATES FORM APPROVED (June 1990) DEPARTMENT OF THE INTERIOR Budget Bureau No. 1004-0135 **BUREAU OF LAND MANAGEMENT** Expires: March 31, 1993 Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM-47168 NOO-C-14 20- 2713 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT--" for such proposals If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well NOV 1 0 1998 X Well Well Other Well Name and No. Name of Operator Eagle Mesa Unit #7 Merrion Oil & Gas Corporation (14634)API Well No. Address and Telephone No. 30-043-20938 610 Reilly Avenue, Farmington, NM 87401-2634 (505) 327-9801 10. Field and Pool, or Exploratory Area Location of Well (Footage, Sec., T., R., M., or Survey Description) Eagle Mesa Entrada 2145' fnl & 645' fwl (sw nw) 11. County or Parish, State Section 13, T19N, R4W Sandoval County. New Mexico 12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Dispose Water (Note: Report results of multiple completion on Completion or Recompletion Report and Log form.) Describe Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Merrion Oil & Gas proposes to continue shut in status for the subject well. The well was drilled in 1997 and the wellbore is in good condition. It is capable of producing significant reserves, however, a submersible pump is required to lift the water and oil. It is uneconomic to repair the sub pump at this time due to low oil prices. We request that long term shut in status be continued until oil prices improve.

I hereby certify that the foregoing is true and correct		
Connie S. Dinning Title Contract Engineer	Date _	11/3/98
(This space for Federal or State office use) Approved By /S/ Duane W. Spencer Title	D-1-	NUV -6 (27)
Conditions of approval, if any:	Date _	