	<b>n 9-</b> 2 pril 19		
	i i		l

## (SUBMIT IN TRIPLICATE)

## Loase No. 1-149 Ind. 8109-A

Indian Agency ... ANYS. 10

Budget Bureau No. 42-R359.4. Approval expires/12-31-60.

## **UNITED STATES** DEPARTMENT OF THE INTERIOR APR / / GEOLOGICAL SURVEY

Riley-College No. 1  WE (M Sec. and Wildest (Field)		located 1929 f  238 (Twp.) San Juan	(F	line :	MTH	ieridian) New ide		sec6
Vell No. 1	is	231 (Twp.)	(F	<b>J</b>	MTH	deridian)		sec6
Vell No	is	238		<b>J</b>	MTH		line of	sec. <u>6</u>
Riley-C	18	located 1990 f	t. from	$\left\{ egin{array}{l} \mathbf{N} \\ \mathbf{s} \end{array} \right\}$ line :	and 1675	ft. from	line of	sec6
	harles						ידי ז	
	(INDI	CATE ABOVE BY CHECK	MARK NAT					, 19
NOTICE OF INTENT	TON TO ABAND	ON WELL	X					
		OR ACIDIZER ALTER CASING		SUPPLEME	NTARY WELL	HISTORY		
		L OR REPAIR WELL	1	H			OR REPAIR	1 1
		E PLANSATER SHUT-OFF	j	11			ACIDIZING	. 1 ./ 1
VOTICE OF INTENT				11		WATER SHUT-		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Drilled to TE 4756' in 1956 and plugged back to 225' and temperarily abandoned. Propose to plug and abandon as follows: Fill hole v/water. Set commat plug from 130' - 100'. 10 ax in top of surface casing. Place 4" regulation marker. Clean and level lecation.

I understand that this plan of work must receive approval in writing by the Geological Survey b Company George Riley, Inc. Address P. 0. Box: 2060 Furnington, liev Mexico

and the second of the second o