

Form 9-331
(May 1965)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other copies to be
retained)Form approved
Bureau Order No. 40-8162

5. LEASE DESIGNATION AND SERIAL NO.

SF-078959

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant, Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FSL 990' FEL Section 7 T24N R7W N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GS, etc.)

7344 KB

10. FIELD AND FORM. OR WILDCAT

Dufers Point Dakota

11. SEC., T., R., M. OR BLK. AND
SURVEY OR AREA

7-24N, 7W N.M.P.M.

12. COUNTY OR PARISH

Rio Arriba, N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and pertinent to this work.)

7-12-80 Perforated with one shot at 6218, 6220, 6224, 6228.

7-14-80 Set packer at 6210. Tried to break down and communicated on backside.
Set packer at 6165. Pressure indicated we were pumping in shale as
well as communicating on backside.

7-15-80 Obtained U.S.G.S. approval to plug and abandon well.

7-16-80 Set 25 sack plug from 5935-6228
Perforated at 3438. Set plug from 3300-3600 and squeezed 3 Bbls. behind pipe.
Perforated at 2130. Set plug from 1900-2200 and squeezed 2 Bbls. behind pipe.
Pumped 40 sacks down bradenhead.
Ran 25 sack plug from the surface to 300'.

7-25-80 Welded dry hole marker.

Attachments: Halliburton job log plugging report.

ACCEPTED FOR RECORD

AUG 21 1980

18. I hereby certify that the foregoing is true and correct.

SIGNED

Harry R. Blythe

HARRISON DISTRICT Resident

(This space for Federal or State office use)

BY

BIO

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

RECEIVED

APR 27 1984

OIL CON. DIV.
DIST. 3

APPROVED

DATE

8/19/80

DATE

JOB LOG

WELL NO.

LEASE

TICKET NO.

CUSTOMER

PAGE NO.

JOB TYPE

DATE _____

FORM 2013 R-2

[illegible]

CUSTOMER