UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	Contract #34
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Jicarilla Apache
THE PEROPE ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to deepen or plug back to a differe eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
eservoir. Oscillation	Jicarilla "C"
1. oil gas other	9. WELL NO.
WCII	16
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Getty Oil Company	Otero Gallup
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
P.O. Box 3360, Casper, Wyoming 82602 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space)	17 AREA
AT SURFACE: 890' FNL & 990' FWL (NW/NW)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: same	Rio Arriba New Mexico
AT TOTAL DEPTH: same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC	CE, -
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DI, ROD, AND HE)
	6715' GR 6724' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF TRECEIV	/FD \ ABB ABB ABB
FRACTORE INC.	
SHOOT OR ACIDIZE REPAIR WELL FEB 001	(NOTE Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE \(\overline{\text{X}}\) \(\overline{\text{U}}\). s. GEOLOGICA	L SURVEY
CHANGE ZONES FARMINGTON,	, N. M. () 4 4 4 4 5 5 7 8 5 2 3
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly	state all pertinent details, and give pertinent dates,
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly including estimated date of starting any proposed work. If wel measured and true vertical depths for all markers and zones per	rinent to this work.)*
measured and true vertical depths for all markers and zones po-	1. foro
Due to an oversight by Getty Oil Company,	this report was not sent before
Due to an oversight by Getty off company, this request is being submitted the work began on this well. Therefore, this request is being submitted	
after the fact.	
	(1) @ 6300
On 3-25-80 we attempted to drill out the	bridge plug (and cement) e 0390
in order to test the Dakota zone. During	this operation, some equipment
was lost in the hole and we fished with n	o recovery. Inis well is culturely
chut in for re-evaluation.	
c - 4 2/4!! hit 5 1/2"	casing scraper, and 4' of 2 3/8" tubing.
The fish consists of a 4 3/4 bit, 5 1/2. The top of the fish is at 6025'.	ment about Sandry notice
The top of the fish is at 6023.	I would the or white and
by July 19, 1982 to report, work	hover, recenque
all and this well.	Set @Ft.
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct Area	
· · · /^	2-1-2
SIGNED Superint	tendent DATE 2-1-
APPOV This pace for Federal or S	State office use)
1120117	DATE
APPROVED BY TITLE TITLE	DATE CONT
CONDITIONS OF APPROVALANT AND 1982.	
AS AMENDED FOR JAMES F. SIMS	SE COLE OF COLE
DISTRICT ENGINEER	The state of the s

See Instructions on Reverse Side