Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ORM APPROVED Budget Bureau No. 1004-0135

		Expires: March 31, 1993
SUNDRY NOTICES AND Do not use this form for proposals to drill or to		5. Lease Designation and Serial No. JIC 34
Use "APPLICATION FOR PE	2 X X X Y 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	6. If Indian, Alottee or Tribe Name
SUBMIT IN TR	RIPLICATE PAPE 2000	7. If Unit or CA, Agreement Designation
1. Type of Well: OIL GAS WELL OTH	ER Z	8. Well Name and Number JICARILLA C
2. Name of Operator FOUR STAR OIL AND GAS COMPANY		6
3. Address and Telephono No. Butler Ave, Ste100 Farmington NM 87461, 325-4397		9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		3003905811
Unit Letter J: 1650 Feet From The SOUTH Line and 1650 Feet From The		10. Field and Pool, Exploratory Area BLANCO MESAVERDE (PRORATED GAS)
EAST Line Section 27 Townsh	p T25N Range R05W	11. County or Parish, State RIO ARRIBA,NM
12. Check Appropriate Box(s) To Indicate Nature of Notice, Re	port, or Other Data
TYPE OF SUBMISSION	· TY	PE OF ACTION
Notice of Intent✓ Subsequent Report	✓ Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Atlering CasingOTHER:	Conversion to Injection
	Unex.	Dispose Water (Note: Report results of multiple completion on Well
FOUR STAR OIL & GAS HAS PLUGGED AND ABANDON THE SUBJECT WELL. 8-9-99 Install Bop, Test Bop and trip out of hole with 2 3/8" tubing. Run in hole with 5 1/2 " cast iron bridge plug, set at 4333". Run in hole with tubing, Set plug #1(4233-4333). Balanced 11 sacks class B cement plug on top of cast iron bridge plug. Pull up hole to 3790". Set plug #2, (3632'-3782') balanced 17 sacks class B cement plug inside casing, pull out of hole and wait on cement. 8-10-99 Run in hole and tag cement at 4091". Pressure test casing to 500 psi. for 5 minutes, held pressure. Set plug 2A, (3632'-3782'), balanced 17 sacks class B cement inside casing, pull up hole to 2841". Set plug #3 (2260'-2841') balanced 66 sacks class B cement inside casing. Set plug #4 (1840'-1990') perforate squeeze holes at 1990'. Set retainer at 1959' placing 68 sacks cement below retainer and 14 sacks cement above retainer. Squeeze to 1200 psi. Set plug #5, (650'-800') Perforate squeeze holes at 800', set retainer at 759'. Place 70 sacks cement below retainer and 12 sacks cement above retainer, circulate to surface, through braden head. Set plug #6 (0'-352') Perforate casing at 352', pump 182 sacks class B cement, circulate to surface. Nipple down BOP, cut off welhead, weld on dry hole marker.		
14. I hereby certify that the foregoing is true and correct SIGNATURE TYPE OR PRINT NAME Rached Hindi	TITLE Senior Engineer	DATE 8/31/99
(This space for Federal or State office use)		
APPROVED CONDITIONS OF APPROVAL, IF ANY:TITLE_	Lands and Mineral Resourc	APR 2 0 2000

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.