	ANTIBLE OF THE INT	SUBMIT IN TRIPLICATES (Other instructions on re- TERIOR verse side)	Form approved. Budget Bureau No. 1004-01. Expires August 31, 1985
	BUREAU OF LAND MANAGE		3. LEASE DESIGNATION AND SERIAL NO
	NOTICES AND REPOR		NM-03746 6. IP INDIAN, ALLOTTEE OR TRIBE NAM
(Do not use this form for Use "/	or proposals to drill or to deepen or APPLICATION FOR PERMIT—" for	plug back to a different reservoir.	
OIL GAS KT	7852	08 532 46 PM 2: 2:	7. UNIT AGREEMENT NAME
Meridian Oil, Inc.		FARMINITAN THE THE ASSA	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR		TARMINGTON, NEW MEXICO	Gilcrease 9. WBGL MO.
P.O. Box 4289 Farm	nington, New Mexico 8	7499	3
4. LOCATION OF WELL (Report location clearly and in accordance see also space 17 below.) At surface 1850'N, 160		any State requirements.	10. FIELD AND POOL, OR WILDCAT
	1050 N, 1000 L		South Blanco PC
			SURVEY OR AREA
4. PERNIT NO.	15. ELEVATIONS (Show wheth		Sec.27, T25N, R3W
	7773'GL	er DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
i. Ch-			Rio Arriba NM
YOU'CE OF	r intention to:	te Nature of Notice, Report, or Ot	her Data
TEST WATER SEUT-OFF		SUPSECE	NT REPORT OF:
PRACTURE TREAT	MULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON*	PRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING
REPAIR WELL	CHANGE PLANS	(Other)Plug back PC	RC FT Coal Y
(Other)	X	(NOTE - Report secults at	multiple completion on Well
Move on location a	nd rig up.		
Kill PC as needed, perfs. Spot 115 g 3627', 3630', 3638 formation with 750 TSTM, frac with 40	ND wellhead, NU BOP. al 7.5% Hcl across per ', 3643', 3645', 3649'	Rum GR-CNL. Set CIBP @ 3 fs. Perforate 10, 0.5" h , 3693', 3698, 3702'. Br /8" balls. Evaluate well lick water. TIH, cleanin	noles @ 3613', reak down
Kill PC as needed, perfs. Spot 115 g 3627', 3630', 3638 formation with 750 TSTM, frac with 40	ND wellhead, NU BOP. al 7.5% Hcl across per ', 3643', 3645', 3649' gals, 15% Hcl & 20, 7,000# and 71,300 gal s	rts. Perforate 10, 0.5" h , 3693', 3698, 3702'. Br /8" balls. Evaluate well lick water. TIH, cleanin	noles @ 3613', reak down
Kill PC as needed, perfs. Spot 115 g 3627', 3630', 3638 formation with 750 TSTM, frac with 40	ND wellhead, NU BOP. al 7.5% Hcl across per ', 3643', 3645', 3649' gals, 15% Hcl & 20, 7,000# and 71,300 gal s	rts. Perforate 10, 0.5" h , 3693', 3698, 3702'. Br /8" balls. Evaluate well lick water. TIH, cleanin	noles @ 3613', reak down for 24 hrs. If ng well out with
Kill PC as needed, perfs. Spot 115 g 3627', 3630', 3638 formation with 750 TSTM, frac with 40	ND wellhead, NU BOP. al 7.5% Hcl across per ', 3643', 3645', 3649' gals, 15% Hcl & 20, 7,000# and 71,300 gal s	rts. Perforate 10, 0.5" h , 3693', 3698, 3702'. Br /8" balls. Evaluate well lick water. TIH, cleanin	noles @ 3613', reak down for 24 hrs. If ng well out with
Kill PC as needed, perfs. Spot 115 g 3627', 3630', 3638 formation with 750 TSTM, frac with 40 gas. Lnad 1 1/4"	ND wellhead, NU BOP. al 7.5% Hcl across per ', 3643', 3645', 3649' gals, 15% Hcl & 20, 7,000# and 71,300 gal s EUE tbg @ 3700'.	rts. Perforate 10, 0.5" h , 3693', 3698, 3702'. Br /8" balls. Evaluate well lick water. TIH, cleanin	noles @ 3613', reak down for 24 hrs. If ng well out with
Kill PC as needed, perfs. Spot 115 g 3627', 3630', 3638 formation with 750 TSTM, frac with 40 gas. Lnad 1 1/4"	ND wellhead, NU BOP. al 7.5% Hcl across per ', 3643', 3645', 3649' gals, 15% Hcl & 20, 7,000# and 71,300 gal s EUE tbg @ 3700'.	rts. Perforate 10, 0.5" h., 3693', 3698, 3702'. Br /8" balls. Evaluate well lick water. TIH, cleaning	noles @ 3613', reak down for 24 hrs. If ng well out with

*See Instructions on Reverse Side

*See Instructions on Reverse Side

*Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.