

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Salco

Marilla Apache

Allotted Cont. #149 Tract #246

Loc. No. Marilla Apache

RECEIVED

JUL 27 1961

Copies:

4-U.S.G.S. Farmington

2-New Mex. Conservation-Aztec, N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY

FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

Notice of Int. to Rep. Leak in

X

Tubing

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 26, 1961

Well No. 7 is located 1550 ft. from N line and 990 ft. from W line of sec. 24

34-34-34-24
(1/4 Sec. and Sec. No.)

25N
(Twp.)

34
(Range)

107W
(Meridian)

So. Rio P. G. & Store Chaves
(Field) Dual Well

Rio Arriba
(County or Subdivision)

N. Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6676 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Propose to:

Rig up pulling unit, pull tubing and repair leak, re-run tubing and put back on production.

Note: On recent Packer Leakage Test well pressures indicated communication between the two zones.

Expect to reappear and put back on production.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amerada Petroleum Corporation

Address Box 1469

Durango, Colorado

By R. F. Furze R. F. Furze

Title Foreman