*

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Approval o	expires	o. 42-R358.4. 12-31-60. TR PG
Land Office	MM	04075
11	H11	1

35

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPO	RT OF WATER SHUT-OFF	X.
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPO	RT OF SHOOTING OR ACHDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OF	SUBSEQUENT REPO	RT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR	WELL SUBSEQUENT REPO	RT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		RT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASIN		ELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			y_\
(INDICATE ABOVE B	Y CHECK MARK NATURE OF REPORT, NOT	ICE, OR OTHER DATA)	
	<u></u>	Ju l y 21st	, 19
Vell No. 10 is located 890	()	()	. 22
NE/4 NE/4 Sec. 22 (4 Sec. and Sec. No.) (Tw	ZON W N	(Meridian)	
S. Blanco PC (Tw	Rio Arriba	New Mexico	
(Field)	(County or Subdivision)	(State or Territory)	
tate names of and expected depths to objective s	DETAILS OF WORK	of proposed casings; indicate mudding j	obs, cemen
5-13-59 TD 100 RKB.		of 8-5/8" OD 24#	J-55
5-13-59 TD 100 RKB. casing at 10 surface.	sends; show sizes, weights, and lengths coints, and all other important proposed Set 3 joints 90' OG' with 70 sacks coop on casing to 500#	of 8-5/8" OD 24# ement, circulated	J -55 to
5-13-59 TD 100 RKB. casing at 10 surface. 5-14-59 Pressured up	sends; show sizes, weights, and lengths coints, and all other important proposed Set 3 joints 90' OG' with 70 sacks coop on casing to 500#	of 8-5/8" OD 24# ement, circulated	J -55 to
5-13-59 TD 100 RKB. casing at 10 surface. 5-14-59 Pressured up in 30 minute.	sands; show sizes, weights, and lengths coints, and all other important proposed Set 3 joints 90' OG' with 70 sacks components of 500% on casing to 500%	of 8-5/8" OD 24# ement, circulated No pressure dec	J -55 to
5-13-59 TD 100 RKB. casing at 10 surface. 5-14-59 Pressured up in 30 minute [understand that this plan of work must receive the company	sends; show sizes, weights, and lengths coints, and all other important proposed Set 3 joints 90' Out with 70 sacks components to 500% on casing to 500% ive approval in writing by the Geological ER DRILLING CORP.	of 8-5/8" OD 24# ement, circulated No pressure dec	J -55 to
5-13-59 TD 100 RKB. casing at 10 surface. 5-14-59 Pressured up in 30 minute [understand that this plan of work must receive the surface of	sends; show sizes, weights, and lengths coints, and all other important proposed Set 3 joints 90' Out with 70 sacks components to 500% on casing to 500% ive approval in writing by the Geological ER DRILLING CORP.	of 8-5/8" OD 24# ement, circulated No pressure dec	J -55 to
5-13-59 TD 100 RKB. casing at 10 surface. 5-14-59 Pressured up in 30 minute 1 understand that this plan of work must receive the pressure of the plan of work must receive the plan of w	sands; show sizes, weights, and lengths coints, and all other important proposed Set 3 joints 90' OG with 70 sacks c on casing to 500# ive approval in writing by the Geologica ER DRILLING CORP. ter Building	of 8-5/8" OD 24# ement, circulated No pressure dec	J -55 to