

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Four Star Oil and Gas Co.

3. Address
3300 N. Butler Ave, Ste100 Farmington NM 87401

3b. Phone No.(include area code)
325-4397

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter I 1750 Feet From The SOUTH Line and 990 Feet From The

EAST Line Section 15 Township T25N Range R03W Meridian: NMPM

5. Lease Serial No.

NM-1142

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement, Name and/or No.
SW-40

8. Well Name and No.
HALL

9. API Well No.
3003905998

10. Field and Pool, or Exploratory Area
TAPACITO PICTURED CLIFFS (PRO GAS)

11. County or Parish, State
RIO ARRIBA, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Attaching Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> OTHER: _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measurements and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operations results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Four Star Oil and Gas Co. has completed the following in the subjecte well. See attachment dated 4/3/02.

14. I hereby certify that the foregoing is true and correct

Name (Printed, Typed)
Arthur D. Archibeque

TITLE Regulatory Specialist

SIGNATURE

DATE 4/8/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/s/ Brian W. Davis

Land and Mineral Resources

Date APR 11 2002

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

04/03/02

Hall # 6

MIRU AZTEC 446. 0 PSI ON TUBING AND CASING. NIPPLE DOWN GULFCO WELL HEAD AND HAD A 8-3/4" HINDERLITER HEAD.

04/04/02

NIPPLE UP FLANGE & BOP'S. PULL 66 STDS 2-3/8" TUBING (3860') RIG UP BASIN WIRELINE AND SET CRBP AT 3836'. TIH WITH OPENENDED TBG TO 3836 AND CIRC HOLE CLEAN. SET 1ST PLUG FROM 3836' TO 3220' WITH 74 SX CL B CEMENT. POOH AND LAY DOWN ALL BUT 1700' OF TUBING. RUN 5-1/2" BAKER FULL BORE PKR AND FOUND HOLE IN 5-1/2" CSG AT 135'. R/U BASIN WL AND PERFORATE AT 1770'. RUN 5-1/2" CMT RETAINER AND SET AT 1724'. MIX AND PUMP 54 SX CLASS B CMT AND PUMP INTO PERFS. LEFT 10 SXS ON TOP OF RETAINER. POOH AND LAY DOWN TUBING. CLOSE BLIND RAMS AND OPEN BRADEN HEAD VALVE. PUMP DOWN 5-1/2" CASING AND CIRC UP THRU BRADEN HEAD VALVE. PUMP 72 SXS CLASS B CEMENT AND CIRC 7 BBLS CMT TO SURFACE. CLOSE BH VALVE AND CASING VALVE. BLM ON LOCATION.