

Removal card

F. Loc. 2610/S; 962/E Elev. 6295 DF Spd. 4/29/53 Comp. 5/20/53 TD 2397 PB
 Casing S. 9-5/8 @ 153 W 100 Sz. Int. @ W Sz. Pr. 7 @ 2355 W 150 Sz. T. @
 Cag. Perf. Shot 150 qts 2367-2397
 #5290 after W/O
 I.P. 1500 MCF/D After 3 Hrs. SICP 941 PSI After 7 Days GOR Grav. Ist Del. 3/5/54 EPNP

TOPS		NITD	Well Log	TEST DATA						
Kirtland		C-102	Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-108	Electric Log							
Pictured Cliffs	2352	C-104	C-110	54	848	489	241	250	486	
Cliff House									411	
Manefee		Ditr	Dfr 2/158/12 - 1119	5/15/55	55687	472	217	345	404	
Point Lookout		Datr 5-31-36	Dac	10/14/55	808	2960	383	404	2877	
Mancos		W/O 6/55. Remarks SOF w/20000 G, 20000 # formerly Superior - Sealy #1-5 correct plate 4 1/2" all over to 10" - 57 R-100 3355 160		5-15-56	767	2836	380	383	2829	
Tecito				5-16-57	665	2129	339	333	2151	#2951
Dakota				7/2/58	578	1741	283	289	1720	
Morrison				7/4/59	552	1545	237	276	1443	
Entrada				7/4/60	529	1388	286	265	1458	
				2/13/61	499	1312	261	250	1347	
				3/4/62	457	1114	250	226	1187	
PC D	3943			4/9/63	456	1086	229	365	598	

S. Blanco PC RA S 5 T 25N R 6W U I Jan. Feb. Mar. Apr. May June July Aug. Sept. Oct. Nov. Dec.
 EPNP Lsc C.I.U. No. 27