be use	form is <u>not</u> to ad for reporting	NEW MEXIC	O OIL CONSERVAT	ION COMMISS	SION	Revised 11-1-58
in Sou	Leakage tests theast New Mexico		NEW MEXICO PACK	1	TEST APACHE	Well No. 10
Operator(_	~ 0,075,D	ENITE O	re Con	4. 14. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12	TIFICIE	
Location of Well: Un		5 Twp. 2	Type of Prod. (Oil or Gas)		Count of Prod. Art. Lift)	Prod. Medium (Tbg. or Csg.)
Upper Completion	PC		1 A/s	Flow		PuBZNG
Lower Completion	moletion CHACRA		LOW SHUT-IN PRE	F/O W		TABENG
	3 - 4 -	Length		SI pre		Stabilized?
Upper Hour, Compl Shut		30 time shu			240	(Yes or No) No
Lower Hour,		Length	of	SI pre		Stabilized?
Compl Shut		26 time shu	t-in /68 #. FLOW TEST NO	es psig	420	(Yes or No) NC
Commenced at	(hour, date)	*	June 2	Zone p	roducing (Upp	er or Lower):
Time	Lapsed time	Pres	sure	Prod. Zone		
(hour, date)	since*	Upper Compl.	Lower Compl.	Тещр.	Re	marks
		226	300		24 HR	AFTER S-I
		235	360		48 HR	11
6-3-25	24 HR	243	220			
6-4-25	48 HR	245	200			
,					-	
Production r	rate during te	esed on	Bbls. in_	Hr	s. Gr	av. GOR
O11:	BOPD b	MCFPD: Tested	thru (Orifice			
Gas.		MID-1	PEST SHUT-IN PR	ESSURE DATA		
Upper Hour, date Length o			of	SI pre		Stabilized?
Compl Shut-in time		time shu	of SI press.		<u></u>	(Yes or No) Stabilized?
Lower Hour,		Length	of	SI pre	:55.	(Yes or No)
Compl Shut	<u>-in</u>	time shi	ut-in FLOW TEST N	psig	<u> </u>	1 (103 01 110)
1 -1	(harra daha)	122		Zone r	roducing (Up)	per or Lower):
Commenced at	(hour, date)	Pre	sgiire	Prod. Zone		
Time	Lapsed time	Unner Comple	Lower Compl.	Temp.		emarks
(hour, date	since **	Opper Compre	HONOT COMPA			
					:	
						3
					Gir.	GOR
					111	85
Production	rate during to	est			\ di	GOR
0il:	BOPD 1	based on	Bbls. in_	Hrs		GUR
Gas:		MCFPD; Teste	Bbls. in d thru (Orifice	or Meter)	•	
REMARKS:						
Minoce	- ALTEC (3) file	harein contains	d is true	and complete	to the best of my
knowledge.			·	or Con	TENONT	16 0=6 Cc
Approved:	Oil Concerns	tion Commission	n Bv	Pat	Do fee	16 056 Cc
New Mexico	Of X DA	Mich			- ENG	
	LEUM ENGINEER		Date		June	_
17012						•

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided bowever, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: If, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- Following completion of Flow Test No. 1, the well shall again be shutin, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3-hour tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period, 7-day tests: immediately prior to the beginning of each flow period, at less one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.
- 24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges, the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.
- 8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test Form Revised 11-1-58, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test Form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the front of the Packer Leakage Test Form.

و و سروی در ارسالیک سي الرمان التاسيد (الرمام 9 \overline{S} 6 0 THE 1111 4 H_T i Eti 711111 111 10 O ### ###