

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	2
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name Lindrith Unit
2. Name of Operator El Paso Natural GAS Company	8. Farm or Lease Name Lindrith Unit
3. Address of Operator Box 990, Farmington, New Mexico	9. Well No. 63
4. Location of Well UNIT LETTER I 1650 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 13 TOWNSHIP 24N RANGE 3W NMPM.	10. Field and Pool, or Wildcat So. Blanco Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) 7004' GL	12. County Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Electric Logs indicate that this well will not be commercially productive, therefore, it is intended to Plug and Abandon in the following manner:

Spot a 60 cu. ft. cement plug from 3180' (total depth) to 2940'. Spot a 68 cu. ft. cement plug from 2840' to 2600'.

Spot a 23 cu. ft. plug in the surface casing.

Install a 4' x 4" dry hole marker and restore the location to original contour.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed **F. H. WOOD**

SIGNED _____

TITLE **Petroleum Engineer**

DATE **5-2-66**

Original Signed by **Emery C. Arnold**

APPROVED BY _____

TITLE **SUPERVISOR DIST. #3**

DATE **MAY 11 1966**

CONDITIONS OF APPROVAL, IF ANY: