

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

RECEIVED

JUL 10 1985

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

830' FNL & 670' FEL

14. PERMIT NO.

API# 30-039-20442

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.

Contract No. 65

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 22

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

W. Lyndrith Gallup-Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 22-25N-4W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

MIRU 6/4/85. Set RBP @ 6830'. Located holes in csg 3413'-3508'. Pressure backside to 1000 psi. Pmpd 100 sxs Dowell 10-3. Flushed tbg. Reversed out. Sqzd away cmt w/final sqz press @ 1000 psi. Rel pkr. Tag cmt @ 3134'. Drilled & washed thru 250' green cmt. Stop 29' above holes. WOC. Finish drlg out cmt. Press test to 1000 psi. Bled off @ 100 psi/min. Located hole between 3445'-3476'. Spotted 30 sxs cmt. Reversed out. Tag cmt @ 3195'. DO cmt. Press test @ 1000 psi. Leaked off @ 200 psi/min. Located holes @ 3476'-3505'. Sqz w/50 sxs class "C" cmt. Reversed out. Rel pkr. DO cmt. Press test, leaked off @ 200 psi/min. Holes @ 3445'-3480'. Pmpd 10 sxs cmt. Rel pkr. Reversed out 12 bbls cmt. Press up to 1000 psi, no leak cmt. Tag cmt @ 3134'. Drilled & washed thru green cmt. to 3354'. WOC. DO cmt. Press. test to 1000 psi, OK. Circ sand off RBP. Swab. Rel RBP. Ran prod. equipment. Placed well on test.

RECEIVED

JUL 15 1985

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DIST. 3

JUL 12 1985

DATE

FARMINGTON RESOURCE AREA

BY

*See Instructions on Reverse Side

NMOCC

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.