

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTRECEIVED
BLMFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS 25 PM 1:54

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

075 FARMINGTON, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325-1821

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 620' FWL

m Sec. 31, T24N, R7W, NMPM

5. Lease Designation and Serial No.

NM 014023

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Betty C 31 #4

9. API Well No.

10. Field and Pool, or Exploratory Area

Lybrook Gallup

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is intended to plug and abandon this wellbore as follows:

- 1.) Set a CIBP above the Gallup perms at 5300'. Cap plug with 8 sks class "B" cement.
- 2.) Pull up hole to 2948'. Spot 12 sks class "B" cement to cover top of Mesaverde. MV top @ 2898'.
- 3.) Pull hole to 1982'. Spot 45 sks class "B" w/4% gel from 1982' to 1252'. Top of Pictured Cliffs @ 1932'. Top of Fruitland @ 1630'. Top of Ojo Alamo @ 1302'.
- 4.) Pull up hole to 350'. Fill casing full with class "B" w/4% gel to surface.

Cut off wellhead and install dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed

Title Operations Manager

Date 4/24/97

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

MAY 01 1997