	l File
OIL CONSERVATION DIVISION P. O. BOX 2088	Form C-103 Revised 19-1-78
SANTA FE SANTA FE, NEW MEXICO 87501	KEA12ER 13 1 10
FILE	5a. Indicate Type of Lease
U.S.G.S.	State Fee XX
OPERATOR OPERATOR	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO WHILE OR FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS XX OTHER-	
iame of Coerator	8. Farm or Lease Name Wright Way
JEROME P. McHugh	9. Well No.
P O Box 208, Farmington, NM 87499	1
ocation of well	10. Field and Pool, or Wildcat
C 950 FEET FROM THE NORTH LINE AND 1680 FEET FROM	Basin Dakota
West Line, SECTION 2 TOWNSHIP 24N RANGE 2W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Hilling In Standard Control of the Asia Contro	Rio Arriba
Check Appropriate Box To Indicate Nature of Notice, Report or Other	her Data
NOTICE OF INTENTION TO: SUBSEQUEN	REPORT OF WE
NOTICE OF WITHOUT PROPERTY.	
RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	LINZAR ABANDONMENT
COMMENCE DRILLING OPNS.	
CHANGE PLANS CASING TEST AND CEMENT JUB	CON. DIV.
	DIST. 3
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
Describe Froposed or Completed Operations (Clearly state all pertinent details, and give permitted work) SEE RULE 1103.	
6-14-83 Ran 210 jts. 4½" 0.D., N-80, 11.6#, LT&C casing. T.E. 8196	5.65' set at 8182' RKB.
Cemented 1st stage with 10 bbls. mud flush followed by 3/U	sx 50-50 poz prus 2%
gel & 6¼# Kolite per sk & ¼# cello flake per sk followed by with ¼# cello flake per sk. (Total cement slurry 1st stage	636 cf). Maximum
cementing pressure 800 psi - Bumped plug with 1500 psi. Fl	loat held OK. Dropped
opening bomb. Opened Dowell stage tool at 5862'. Cemented	d 2nd stage with 10
bbls. mud flush followed by 2/5 sx 65-35 plus 12% gel and b	54# Koliteper sk and
14# cello flake per sk followed by 310 sx 50-50 pso plus 2%	gel and 4# cello
flake per sk. (Total cement slurry 2nd stage 1038 cf). Op 3578'. Cemented 3rd stage with 10 bbls mud flush followed	hy 500 sx 65-35 plus
12% gel & ½# cello flake per sk followed by 100 sx 50-50 pg	os plus 2% gel and ¼#
collo flake ner sk (Total cement slurry 3rd stage 1245 cf).	. Closed stage tool
with 2500 psi. Held OK. Job complete at 8:45 a.m. 6-13-8.	3. Set 4½" casing
slips. Cut off casing and released rig at 10:45 a.m. 6-13-	-63.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Agent Agent	6-21-83
GNEO JIMIL. Jacobs	
Original Signed by FRANK T. CHAVEZ	JUN 2.2 1983