	PARTMENT OF THE INTERIOR CONTROL OF LAND MANAGEMENT	SF-081296
SUNDRY (Do not use this form Use	NOTICES AND REPORTS ON Word proposals to drill or to deepen or plug back to a "APPLICATION FOR PERMIT—" for such proposals.)	/ELLS different reservoir.  7. UNIT AGREEMENT NAME
1. OIL PT GAS		(. UNIT AVABENTET NAME
WELL WELL	OTHER	8. FARM OR LEASE NAME
E. Alex Phillips	Federal	
3. ADDRESS OF OPERATOR		9. WBLL NO.
1200 Philtower B	Gavilan #2	
4. LOCATION OF WELL (Report See also space 17 below.)	location clearly and in accordance littens Statered	
At surface	7 per DEC S	Gav. Mancos/ DK/Grant
1846 FEL and 182	/ rsL	SURVEY OF AREA
Section 26, T	25N, R2W, NMPM BUREAU OF LAND	MANAGEMENT 26-25N-2W, J
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, OR, or	
	7404	Rio Arriba "NM
TEST WATER BRUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)  17. DESCRIBE PROPUSED OR COMP proposed work. If well nent to this work.) *  10/29 - 10/31/84  11/01 - 11/13/84  11/14/84	NULTIPLE COMPLETE  ABANDON* CHANGE PLANS  CH	Grnhn loading up, Gallup isn't pumping ds and tubing on short string (Gallup)
11/15 - 11/18/84	mud, sand and water)	tring, blew down with N2 (recovered
11/19 - 11/20/84	natural. Found no increase	25 holes @ 1' above originals. Tested and treated Gallup @ 10 BPM down tubing 5,000 gals.(23,000 gallons foam) ISDP,000#.
11/20/84	Flowing and swabbing Gallup	
12,20,01		DEC 10 loa
		OLUM SIV.

\*See Instructions on Reverse Side