5. LEASE

UNITED JEATES DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for pegasate to office or to desegn or plug back to a office of the control with form \$30\$-Core start proposate. 2. NAME OF OPERATOR SOUTHETH Union Exploration 3. P.O. Box 2179 Farmington, NM 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See Space 17) ADDRESS OF OPERATOR A TOTAL DEFTH: 420' FSL 5 1850' FEL AT TOTAL DEFTH: 420' FSL 5 1850' FSL	DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	31carilla Contract # 145 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. oil gas Ex Other 2. NAME OF OPERATOR Southern Union Exploration 3. ADDRESS OF OPERATOR P.O. BOX 2179 Farmington, NM 87499 P.O. BOX 2179 Farmington, NM 87499 A1 SURFACE: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 100 PROD. INTERVAL: 420' FSL & 1850' FEL AT 101AL DEPTH: 420	SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
1. oid well Bas State St	eservoir. Use Form 9-331-C for such proposals.)	<u> </u>
22A 22A 22A 22B 22A 22B 22A 22B 2	.] [1] ⁶ 7 o é b o e	
3. ADDRESS OF OPERATOR P.O. Box 2179 Farmington, NM 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below). AT SURFACE: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOTAL CEPTH: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FSL	Well — Well Stills	
3. ADDRESS OF PERALOR P. O. Box 2179 Farmington, NM 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below). AT SURFACE: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP ALCEPTH: 420' FSL & 1850' FEL ALCEPTH: 420' FSL & 1850' FS	Southern Union Exploration	
A. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below). AT SURFACE: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOP PROD. INTERVAL: 420' FSL & 1850' FEL AT TOTAL DEPTH: 420' FSL & 1850' FEL 18. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPORT OF: FRACTURE TREAT SHOT OR ACIDIZE CHANGE OF ACIDIZE REPORT OF: TOTAL OF APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE CHANGE TONES CHANGE OF THE PULL OF ALTER CASING FRAMINGTON OR ACIDIZE CHANGE TONES CHANGE OF THE PULL OF ALTER CASING FRAMINGTON OR ACIDIZE CHANGE TONES CHANGE OF THE PULL OF ALTER CASING FRAMINGTON OR ACIDIZE CHANGE AND PROPER SHOOT OF THE PULL OF ALTER CHANGE OF THE PULL OF ALTER CASING FRAMINGTON OR THE PULL OF ALTER CASING FRAMIN	3. ADDRESS OF OPERATOR P.O. Box 2179 Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
AT SURFACE: 420' FSL & 1850' FSL AT 10P PROD. INTERVAL: 420' FSL & 1850' FSL AT 10P PROD. INTERVAL: 420' FSL & 1850' FSL AT 10P PROD. INTERVAL: 420' FSL & 1850' FSL AT 10P PROD. INTERVAL: 420' FSL & 1850' FSL AT 10P PROD. INTERVAL: 420' FSL & 1850' FSL AT 10P PROD. INTERVAL: 420' FSL & 1850' FSL AT 10P PROD. 10P PR	4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 420' FSL & 1850' FEL AT AT TOTAL DEPTH: 420' FSL & 1850' FEL AT AT TOTAL DEPTH: 420 ACCUPATIONS AND NOT: 430' FSL & 1850' FEL AT TOTAL DEPTH: API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6597		
AT TOTAL DEPTH: 420' FSL & 1830' FEL 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, WILL BOX ALTER CASING BOX ACIDIZE BOX APPROVAL TO: 17. CHANGE ZONES BOX ADANDON' (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and give pertinent to this work.)* 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dothis change on form 9-330.) 18. Spud 12½ "Surface hole @ 4:30 pm, 8/24/84. Drilled to 321. Ran 7 jt (3	AT TOP PROD INTERVAL: 420' FSL & 1850' FEL) i
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON' (other) drilled and cased TO DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6¼#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve Manu and Type 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. 101 In the proposition of the proper state office use)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE COMPLETE COMPLETE OCHANGE ZONES ABANDON* (other) drilled and cased FARMINGTON 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84 Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve Manu. and Type TITLE Division Engineer DATE September 4, 1984	16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF TRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PLUL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON' (other) drilled and cased DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 64#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valvew Manu. and Type Set @ Ft. TITLE Division Engineer DATE September 4, 1984	REPORT, OR OTHER DATA	
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) drilled and cased PERMINISTON BUREAU OF LIND FARMINISTON BUREAU OF LIND FARMINISTO	REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) drilled and cased DURGE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Manu. and Type 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. SIGNED CHARLES AND		
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) drilled and cased BUREAU OF LAND SEPTION 1330 BUREAU OF LAND BUREAU OF LAND BUREAU OF LAND BUREAU OF LAND SEPTION 1330 BUREAU OF LAND SEPTION 1330 BUREAU OF LAND BUREAU OF LAND SEPTION 1330 BUREAU OF LAND SET OF SAME OF SUMBLE OF SAME	SUCOT OR ACIDIZE	
PULL OR ALTER CASING MULTIPLE COMPLETE MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) drilled and cased PARMINGTON 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. Subsurface Safety Valve: Manu. and Type 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. SIGNED ON TITLE Division Engineer DATE September 4, 1984	REPAIR WELL B REC	(NOTE: Report results of multiple completion or zone
CHANGE ZONES ABANDON* (other) drilled and cased BUREAU OF LAND FARMINGTON 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½ surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl2 & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Manu. and Type 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. SIGNED TITLE Division Engineer DATE September 4, 1984	PULL OR ALTER CASING	change on Form 9-330.)
BUREAU OF LAND (other) drilled and cased BUREAU OF LAND FARMINGTON 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Manu. and Type 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. SIGNED Of the proposed to the foregoing is true and correct TITLE Division Engineer DATE September 4, 1984	MULTIPLE COMPLETE LI SEL	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Wanu. and Type Subsurface Safety Valve: Wanu. and Type TITLE Division Engineer DATE September 4, 1984	ABANDON*	LAND WAS STORY
including estimated date of starting any proposed work. If we list directionally diffuse measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Spud 12½" surface hole @ 4:30 pm, 8/24/84. Drilled to 321'. Ran 7 jt (3 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cmtd w/236 cuft (200 sk) Class B Cement w/ 2% CaCl ₂ & ½#/sk flocele. Circulate 14 bbl cement. 2. WOC 12 hr. N.U. BOP. Pressure test to 800 psi OK. drilled out surface & 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Manu. and Type	(other) drilled and cased FARMINGTO	Z salotti (1978)
8 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/84. 3. Ran GR-Induction and Density logs TD @ 5556'-to surface. 4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; 1st:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Manu. and Type	including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine 1. Spud 12½" surface hole @ 4:30 pm, 8/24/8 8 5/8", 32.0#, K-55, Csg & set @ 315'. Cement w/ 2% CaCl ₂ & ½#/sk flocele. Cir 2. WOC 12 hr. N.U. BOP. Pressure test to	ont to this work.)* 4. Drilled to 321'. Ran 7 jt (302') Cmtd w/236 cuft (200 sk) Class B culate 14 bbl cement. 800 psi OK. drilled out surface casing
4. Ran 4½" 11.6#, K-55 (5560'-4253') & 4½", 10.5#, K-55 csg (4253-surface) Cemented in 3 stages; lst:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Subsurface Safety Valve: Manu. and Type 5. Ran temperature survey 9:00 am, 9/3/84 to locate Top of cement @ 1400'. 18. I breely rentify that the foregoing is true and correct SIGNED OF Church Property of Federal or State office use)	& 7 7/8" to 5560'. TD @ 2:00 p.m. 9/1/8	4.
Cemented in 3 stages; lst:325 cuft 50/50 poz, 2% gel, 8# sk salt; 2nd: 130 cuft 50/50 poz, 2% gel, 8#/sk salt; 3rd: 400 cuft 65/35 poz, 6% gel, 6½#/sk gilsonite. Plug down @ pm 9/2/84. Set slips w/ 50,000# & cut of excess csg. Released Rig. Set @	3. Ran GR-Induction and Density logs TD @ 5556'-to surface.	
Ran temperature survey 9:00 am, 9/3/84 to locate lop of tement e 1400. 18. I hereby certify that the foregoing is true and correct SIGNED TITLE Division Engineer DATE September 4, 1984	Cemented in 3 stages; lst:325 cuft 50/5130 cuft 50/50 poz, 2% gel, 8#/sk salt; 6½#/sk gilsonite. Plug down @ pm 9/2/8 excess csg. Released Rig.	3rd: 400 cuft 65/35 poz, 6% gel, 34. Set slips w/ 50,000# & cut off
SIGNED SIGNED TITLE Division Engineer DATE September 4, 1984	Subsurface Safety Valve: Manu. and Type 9.00 am 9/3/84	To locate Top of cement @ 1400'.
SIGNED SIGNED TITLE Division Engineer DATE September 4, 1984	18. I bereby certify that the foregoing is true and correct	
	SIGNED Schweifer TITLE Division Eng	ineer DATE <u>September 4, 1984</u>
	his space for Federal or State of	office use)
SEP 2 4 1984 SEP 2 1 1984 SEP 2 1 1984		ACCEPTED FOR RECORD
SEP 24 1984	(D) L 3	
*See Instructions on Reverse Side	M SEP 2 4 130-	SEP 2.1 1984
TARimmering in the party of the	See Instructions on Revers	e Side
OIL DIST. 3	OIL DIST. 3 NMOCC	FARMINGTON BESSONGE AREA