

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. Contract 126/29
2. NAME OF OPERATOR Apache Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
3. ADDRESS OF OPERATOR 1700 Lincoln, Ste. 1900, Denver, CO 80203-4519		7. UNIT AGREEMENT NAME N/A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 718' FSL, 2035' FEL		8. FARM OR LEASE NAME Apache
14. PERMIT NO.		9. WELL NO. #144
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6843' GR		10. FIELD AND POOL, OR WILDCAT Lindrith Gallup Dak. W.
		11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA Sec. 13-24N-R4W
		12. COUNTY OR PARISH Rio Arriba
		13. STATE NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) Recompletion ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Apache Corporation requests permission to recomplete the above captioned well in the Gallup formation. Attached please find the proposed procedure for this work.

RECEIVED

DEC 31 1990

OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

David M. Talbott

TITLE

Sr. Operations Engineer

DATE

11/14/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DEC 24 1990

AREA MANAGER

\*See Instructions on Reverse Side

Apache #144  
SW SE Sec 13-T24N-R4W  
Recompletion to Gallup  
November 14, 1990

- A. MIRU SU
- B. KILL WELL AS REQUIRED
- C. ND WH & PL EQUIPMENT
- D. NU BOP
- E. TOOH W/ TBG
- F. SET WIRELINE SET TBG RETRIEVABLE BP
  - 1. RU WIRELINE COMPANY
  - 2. RUN GAUGE RING TO 6348'
  - 3. SET HALLIBURTON WSTR-BP @ 6338'
- G. PRESSURE TEST TO 3000 PSI
- H. DUMP BAIL 1 SX SD ON BP

NOTE: Check w/ BP & Wireline company about which type of bailer required. Glass btm w/ blasting cap or Glass btm w/ plunger

- I. PERFORATE
  - 1. Correlate and perforate w/ csg gun DIL depths w/ 2 jspf as follows:
    - a) 6240-6254'
    - b) 6268-6276'
    - c) 6280-6288'
- J. RD WIRELINE COMPANY
- K. BREAK DOWN PERFS
  - 1. TIH W/ RTTS PKR
  - 2. RU SERVICE COMPANY
  - 3. PUMP ACID W/ BALLS PER ATTACHED RECOMMENDATION
  - 4. TOOH W/ RTTS PKR
- L. FRAC GALLUP PERFS
  - 1. RU SERVICE COMPANY
  - 2. FRAC GALLUP PER SERVICE COMPANY PROCEDURE
  - 3. RD SERVICE COMPANY
  - 4. SI PER SERVICE COMPANY RECOMMENDATION
  - 5. FLOW BACK UNTIL DEAD

M. CLEAN OUT SAND & BALLS

N. RETREIVE BP

O. TIH W/ PRODUCTION STRING

P. RU TO SWAB WELL UNTIL CLEAN

Q. RIG TO RUN PUMP AND RODS

R. RU PU

S. RETURN WELL TO PRODUCTION