Form 3160-5 (November 1983) . (Formerly 9-331) DEF	UNITED STA	NITED STATES SUBMIT IN TRIPLICAT (Other instructions on verse side)		
BUREAU OF LAND MANAGEMENT				SF-078534
SUNDRY	NOTICES AND R	EPORTS ON	WELLS to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.				7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER 2. NAME OF OPERATOR				8. FARM OR LEASE NAME
JACK A. COLE				RINCON
3. ADDRESS OF OPERATOR				9. WELL NO.
P. O. BOX 191, FARMINGTON, NEW MEXICO 87499 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF WELL (Report II See also space 17 below.) At surface	ocation clearly and in accord	uance with any but	ec volumement.	LYBROOK GALLUP 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
865 FSL x 990 FWL				SW 4 SW 4 SEC. 31-T24N-R6W 12. COUNTY OR PARISH 13. STATE
14. PERMIT NO.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7062 GR 7076 KB			RIO ARRIBA NEW MEXICO
16. Ch			ure of Notice, Report, or (Other Data
NOTICE	OF INTENTION TO:		BUBBEQ	QUENT REPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OB ACIDIZE	PCLL OR ALTER CAS MULTIPLE COMPLET ABANDON®		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL ALTERING CASING ABANDONMENT®
REPAIR WELL	CHANGE PLANS		. Mannet Banant Banant	T SURFACE CASING X
(Other)			Completion or Recom	pletion Report and Log form.)- s. including estimated date of starting any cal depths for all markers and zones perti-
nent to this work.)	1989 - Spud 6 8 5/8" with 2 Flocel	:30 PM. Se 24# J-55 50 sx clas	et 6 joints (257) Casing at 272.1 ss "B", 3% CaCl ₂ Late 95 sx. Plug	.17 ft.) of .7 ft. Cement ., and ½1b/sx
24 SEPTEMBER	1989 - Pressu for 15	re Test ca minutes.	asing and B. O. Test O.K.	P. to 500 PSI
				UUT1 91939
				dist. 3
18. I hereby certify that the r	oregoing is true and correct		ROLEUM ENGINEER	DATE 25 SEPTEMBER, 19
SIGNED				
(This space for Federal or	: State omce use)			DATE
APPROVED BY	VAL IF ANY:	TITLE		ACCEPTED FOR RECORD
COMPLITIONS OF MAILING		- 	100	PCT 1 7 1989

3

*See instructions on Reverse Side

OCT 1 7 1989
FARMINGTON RESOURCE ARE: