Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVE Budzet Bureau No. 1604-0135

3. Lease	nesignation	ETAS	Seria	J No.
JIC	149			
6. If Ind	ian, Allottee	or 1	Tribe	Name

SUNDRY	NOTICES	AND	REPOR	RTS	ON	WELLS

Use "APPLICATION FO	R PERMIT—" for such proposals	Jicarilla Apache
SUBMIT	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil X Gas Well X Well Other		8. Well Name and No.
2. Name of Operator Amerada Hess Corporation 3. Address and Telephone No.		Jicarilla Apache "F" #16
Drawer D, Monument, New Mexic	co 88265 505 393-2144	30-039-25256 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey D	escription)	W. Lindrith Gallup Dakot
970' FNL & 800' FEL, Sec. 17	, T25N, R5W	11. County or Parish, State
		Rio Arriba, N.M.
2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Plugging Back	New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection
©IL COM	a Divio	_ Dispose Water

Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plan to MIRU pulling unit & install BOP. TIH w/RBP on 2-3/8" tbg. & set at 7100'. Drop 4 sks. 12/20 sand on RBP. Press. test RBP & csg. to 3700 PSI. TIH w/4" csg. guns & perf. 5-1/2" csg. w/4 SPF fr. 7002' - 7016'. Break down perfs. fr. 7002' - 7016' w/2% KCL water w/clay stabilization & surfactant additives. Set 5-1/2" pkr. at \pm 6950'. MIRU Halliburton & hydraulically frac treat perfs. fr. 7002' - 7016' w/approx. 45,000 gal. 35# Hybor XL Guar Gel & 220,000 lbs. 20/40 Ottawa Sand @ 35 BPM. Flow test well. TIH, clean sand off RBP, latch onto RBP & TOH. TIH w/2-3/8" Texas pattern collar, 2-3/8" sub & 2-3/8" profile nipple on 2-3/8" tbg. Run 1-1/2" check valve in place. Set tbg. OE at + 7125'. Remove BOP & install wellhead. RDPU & clean location, fish check valve & evaluate production.

14. I hereby certify that the foregoing is true and correct Signed L While J	Tide Admin. Svc. Coord.	Date 11-14-95
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Chief, Lands and Mineral Resources	JAN 2 5 1996 Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.