

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED  
BLM

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

070 FARMINGTON, NM

5. Lease Designation and Serial No.

NM-95616

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Rincon Largo Fed 24 # 2

9. API Well No.

30-139-25715

10. Field and Pool, or Exploratory Area

Devils Fork Assoc

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Csg Sundry

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spud well @ 12:30 a.m. 5/6/98. Drilled 12 1/4" hole to 338' KB. Ran 8 jts. 8 5/8", 24#, J-55, ST&C casing measuring 321.54' set @ 333.54' KB. Cemented w/300sx(354 cuft) Class "B" cement. Circulated 6 bbls to surface. Plug down @ 10:15 a.m. 5/6/98. Bump plug to 500 psi. Held fine. WOC 12 hrs.

Drilled 7 7/8" hole to 5645' KB. TD reached @ 1:17 a.m. 5/15/98. Ran 130 jts 4 1/2", 10.5#, J-55, LT&C casing measuring 5654.22' set @ 5644.22' KB. Cemented w/1130 sx(1334 cuft) 50/50 poz cotaining 2% gel, 1/4# per sk Flocele and .3% Halad 344. Circulated 3 bbls to surface. Bump plug to 500 psi. Plug did not hold. Bumped a second time and plug held fine. Plug down @ 4:15 p.m. 5/16/98. Currently waiting on completion.

14. I hereby certify that the foregoing is true and correct

Signed Rory Embury Title Operations Manager

Date 6/2/98

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

ACCEPTED FOR RECORD

JUN 15 1998

FARMINGTON DISTRICT OFFICE

BY

\*See Instruction on Reverse Side

NMOCD