



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Monte 70
Lease No. SF-078562
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT - <u>Dakota Form X</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, 19 60

LAND OFFICE
Well No. 43 is located 1070 ft. from N line and 810 ft. from E line of sec. 19
NE/4 NE/4 Sec. 19 T24N 6W 54PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Devils Fork Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6782 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing, and cementing points, and all other important proposed work)

Set Baker cast iron bridge plug at 6,419'. Pressured casing and bridge plug w/4000#. Held OK. Filled hole with sand from 6,419' to 6,000'.
Dakota temporarily abandoned.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bedfern & Hard Inc.
Address Box 1747
Midland, Texas
By Original signed by T. A. Dugan
Title Consulting Engineer