DEPARTMENT OF THE INTERIOR

FORM APPROVED

Budget Bur	eau No.	1004	1-0135
Expires:	March	31, 1	993


BUREAU OF LAND MANAGEMENT		Expires: March 31, 1993
CUNDRY NOTICE	C AND DEPORTS ON MELLS	5. Lease Designation and Serial No.
• • • • • • • • • • • • • • • • • • • •	S AND REPORTS ON WELLS odrill or to deepen or reentry to a different reservoi	
• •	FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name
		JICARILLA TRIBAL
	•	7. If Unit or CA, Agreement Designation
1. Type of Well		
Oil Ses Other		8. Well Name and No.
2. Name of Operator	Attention:	JICARILLA CONTR 146 #15
Amoco Production Company	WAYNE BRANAM, RM	1220 9. API Well No.
 Address and Telephone No. P.O. Box 800, Denver, Colorado 8020 	11	OTERO CHACRA (GAS) 10. Field and Pool, or Exploratory Area
		3003982336
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
940 FSL 1450FWL	Sec. 09 T 25N R 5W UNIT N	N Rio Arriba New Mexico
12. CHECK APPROPRIATE I	BOX(s) TO INDICATE NATURE OF NO	TICE , REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	ACTION
	I♥I	
Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Aftering Casing Other	Conversion to Injection Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form. I
		date of starting any proposed work . If well is directionally drilled, give
	spths for all markers and zones pertinent to this work.)* ABANDON THIS WELL PER THE ATTACHED	PROCEDURE.
		•
		:
		同國多国门》目 1
		A JUL 1 5 1994
		•
		onl con. div.
		Dist. 3
		Suppression the state and are severe as a severe of the state of the s
14. I hereby certify that the foregoing is trye and correct		
Signed / Mys Signed	Title BUSI	NESS ANALYST Dete 06-16-1994
This space for Federal or State office use)		
da A	Ading Chief, Lands	and Mineral Resources JUL 1 3 1994
Approved by Joyan A. Le Conditions of approval, if any:	Title	Date
a annual and approximation will to	U	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.

PXA Procedures Jicarilla Contract 146 #15

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well.
- 3. POOH with 2 3/8" tbg. RIH with tbg and cement retainer. Set retainer at 3730' and squeeze perfs from 3781' to 3795' with 24.436 cuft cement. Pull out of retainer and spot cement plug to 2700' with 369.36 cuft cement.
- 4. RIH with perf gun and shoot squeeze holes at 2310'. RIH with cement retainer, set retainer at 50' above squeeze holes and attempt to circulate to surface with 1052.436 cuft cement. Pull out of retainer and fill hole to surface with 310.26 cuft cement.
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

JICARILLA CONTRACT 146-15 9N-25N-5W SINGLE OC ORIGINAL COMPLETION DATE 11/62 LAST FILE UPDATE 5/94 BY CSW



CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator AMOCO PROD COMPANY Well Name JIC CONT 146 #15

- Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Albert Naquin with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Squeeze holes will be placed at 2360 ft. instead of 2310 ft. If cement does not circulate to the surface from 2360 ft., the casing will be perforated at the appropriate depths to insure that the Nacimiento Formation is covered and cement is placed in the annulus from 50 ft. below the casing shoe to the surface.