

Form 3160-5
June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

SF 078859

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325-1821

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL - 640' FWL
Sec. 15, T24N, R9W, NMPM

7. If Unit or CA, Agreement Designation

8. Well Name and No.

South Huerfano 1

9. API Well No.

30-045-05107

10. Field and Pool, or Exploratory Area

Bisti Gallup

11. County or Parish, State

San Juan, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Report

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plug and abandon this well as follows:

- 1.) Set CIBP @ 5160'. Cap with 100' cement to cover Gallup.
- 2.) Spot plug inside casing from 2287-2537' to cover Mesaverde top at 2487'.
- 3.) Perforate 2 holes at 1685'. Pictured Cliffs top at 1635'. Spot plug inside and outside casing from 1685' to 927' to cover Pictured Cliffs, Fruitland and Ojo Alamo tops.
- 4.) Perforate at 350'. Establish circulation to surface. Fill inside and outside of casing full with class "B" cement with 4% gel.
- 5.) Cut off wellhead & installed dry hole marker.

I hereby certify that the foregoing is true and correct

Signed

Title Operations Manager

Date

11/4/96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

APPROVED

NOV 07 1996
/S/ Duane W. Spencer
DISTRICT MANAGER