Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on re-

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY	NM-0557389	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTE	E OR TRIBB NAME

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)		
OIL GAS OTHER	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR BCO, Inc.	S. FARM OR LEASE NAME. Nancy.	
3. ADDRESS OF OPERATOR P. O. Box 669 Santa Fe, New Mexico 87501	9. WELL NO.	
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 	Undes. Mancos Dakota	
2310' FNL 1980' FWL Section 12 T24N R8W NMPM	Sec. 12 24N 8W NMPM	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE	

GR 7287 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data ...

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT! CHANGE PLANS REPAIR WELL (Norn: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) Perforate & frac

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per nent to this work.)*

- 1. Log cement.
- 2. Perforate Graneros and Skelly.
- Sand water gel frac Graneros formation. 3.
- Set retrievable bridge plug below Skelly & above Mary.
- Sand water gel frac Skelly formation. 5.
- 6. Remove retrievable bridge plug and place well back into production.



18. I hereby certify that the foregoing is true and correct Chairman TITLE

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side