

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NMO-554922
2. NAME OF OPERATOR Kirby Exploration Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 1745, Houston, Texas 77001		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1450' FEL and 1020' FSL		8. FARM OR LEASE NAME Smith Federal
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6785 GL		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec 26, T24N, R10W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input checked="" type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Completion	<input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled 6 $\frac{1}{4}$ " hole to 1450. Total depth at 4:00 p.m. 9-14-76. Ran Open hole logs, IES and FDC-CNL, GR and Caliper. Ran 35 joints 4 $\frac{1}{2}$ " O. D. 11.6# casing and set at 1413 feet. Cemented with 100 sacks class "A" with 2% CaCl<sub>2</sub>. Bumped plug at 5:00 p.m. 9-17-76. Wait on cement. 9-20-76 Rigged up completion unit. Rigged up Dresser Atlas. Ran correlation log. Ran tubing and blew well bore dry with N<sub>2</sub>. Perforated 1278 - 1300 and 1302-1314 with three tubing guns. 9-21-76 thru 9-24-76 Swabbed well - no shows. Acidized with 3000 gallons Dowell "gas well" acid. 9-25-76 to 9-27-76. Swabbed well - no shows.

SEP 30 1976

18. I hereby certify that the foregoing is true and correct

SIGNED William T. Jones TITLE Agent DATE 9-29-76  
(This space for Federal or State office use)APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side