5 MMS 1-File 1-Andes Form approved. Budget Bureau No. 1004-0135 Form 3160-5 UNITED STATES SUBMIT IN TRIPLICATE. DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side) Expires August 31, 1985 (November 1983) CEASE DESIGNATION AND BERIAL NO. (Formerly 9-331) BUREAU OF LAND MANAGEMENT NM-1008**9** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME WELL X WELL | OTRER 8. FAEM OR LEASE NAME 2. NAME OF OPERATOR Mary Anne Dugan Production Corp. 9. WELL NO. 3. ADDEES OF OPERATOR P.O. Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface 10. FIELD AND POOL, OR WILDCAT Bisti Gallup 11. SEC., T., R., Y., OR ELK. AND ECEVEY OR AREA 790' FWL - 1650' FSL APP No sto Sec. 9, T24N, R9W BUREAU OF LARD 1 12. COUNTY OR PALISH | 13. STATE 14. PERMIT NO. 6677 'GL 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SCENEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT SHOOTING OR ACIDIZING ABANDONMENT[®] ABANDON® SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Plug Back 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and gones perti-This well is a commingled producer from the Dakota formation and Gallup formation. Dakota is now producing water and creating a production problem. We propose to plug the Dakcta and produce the well as a single Gallup producer as follows: Pull rods and tubing. Set cast iron B.P. @ 6278' (50' above Dakota perfs). 3. Dump 50' of cement with Dump bailer on plug. Re-run rods and tubing and pump well as Gallup single completion. APPROVED 18. I hereby certify that the foregoing is true and correct DATE 4/4/85 Jim L. Jacobs (This space for Federal or State office use) APR Q 8 1985 APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

FARMINGYON RESOURCE AREA